

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliate data Fadaustian Internationale Dea Franceto Fo Automobile    |   |   |                 |                       |  |
|--|---|---|-----------------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile      |   |   |                 |                       |  |
| MS   | LIBERTY INSURANCE PTE LTD               |   | Ref:            | CS/LIP24110564/Knh3e2 |  |
|  | ONE RAFFLES QUA<br>SINGAPORE 04858      | JAY #25-01 NORTH TOWER<br>83                  | Date:           | 10/12/2024            |  |
|  |   |   | Code:           | LIP                   |  |
| 1.   | Policy Particulars :- THIRD PARTY CLAIM |   |                 |                       |  |
|  | Insured Veh.                            | SNH 419T                                      | Veh. Inspected  | SNL 5332E             |  |
|  | Policy No.                              | -   | Coverage        | 0                     |  |
|  | Claim No.                               | AVS24/3675                                    | Excess          | \$0.00                |  |
|  | Assign From                             | CMPU  | Assign Date     | 26/11/2024            |  |
| 2.   | 2. Vehicle Details                      |   |                 |                       |  |
|  | Make & Model                            | TOYOTA WISH (A)                               | C.C             | 1798                  |  |
|  | Engine No.                              | 2ZR1836339                                    | Year of Reg.    | 28/09/2016            |  |
|  | Chassis No.                             | JTDGG20W10J005258                             | Colour          | WHITE                 |  |
|  | Odometer                                | 162689 KM                                     | Steering        | IN ORDER              |  |
|  | Brakes                                  | IN ORDER                                      | General         | GOOD                  |  |
|  | Modification(s)                         | RIMS: SPORTS RIM                              |                 |                       |  |
| 3. Conditions of Tyres   |   |   |                 |                       |  |
|  |   | Size  | Make            | Balance (mm)          |  |
|  | R/H Front Tyre                          | 215/50R17                                     | MICHELIN        | 8                     |  |
|  | L/H Front Tyre                          | 215/50R17                                     | MICHELIN        | 8                     |  |
|  | R/H Rear Tyre                           | 215/50R17                                     | MICHELIN        | 8                     |  |
|  | L/H Rear Tyre                           | 215/50R17                                     | MICHELIN        | 8                     |  |
| 4.   | 1. Description of Damages               |   |                 |                       |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.                 |   |   |                 |                       |  |
| DAMAGES SEE DETAILS.   |   |   |                 |                       |  |
| 5.   | General Information                     |   |                 |                       |  |
|  | Accident Date                           | 24/11/2024                                    | Inspection Date | 27/11/2024            |  |
|  | Survey held at                          | THIAM HENG HUAT PTE LTD                       | •               |                       |  |
|  |   | 176 SIN MING DRIVE<br>#05-14 SINGAPORE 575721 |                 |                       |  |
| 5a.  | Remarks                                 |   |                 |                       |  |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.         |   |   |                 |                       |  |
| B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |   |                 |                       |  |
| 5b. Estimate Days of Repair  |   |   |                 |                       |  |

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days