

A.S. REC. BY:

REF:

LIP /

CS / Lip 24110564 / knh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNL 5332 E

Yr Regn:

09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

C.C.

MPV

1798

Colour

White

A/C:

Insured / Std / NI / NA

Sp.Reading

162689

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDG620W 10J005258

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size:

F:

215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

24/11/24

D.O.I.

27/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / EM not ready

2/12 Lip 815501 Cahn (Red. \$ 3694.50, 70%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Notified
11 Sep @ 1550h
Penny After Pain
3 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SNL 5332E

Acc: 24.11.24

S/N Parts Description

- 1 Taillamp RH
- 2 Rear fender RH
- 3 Rear fender glass with midg RH
- 4 Rear bumper assy
- 5 Rear bumper relector RH
- 6 Rear bumper retainer white
- 7 Rear bumper retainer black

Unit Price Amt

Wt \$556.00 ✓
n \$940.00 X
na \$450.60 X
Bul cm \$595.00 ✓
cm \$72.10 ✓
cm \$108.20 ✓
cm \$192.60 ✓

258

Special Nett

- 1 Rear bumper clips
- 2 Rear fender glass sealant

na \$50.00 ✓
na \$80.00 X

Labour

- 1 To cut/weld and remove and refit damaged parts
- 2 To spray paint on affected parts
- 3 To remove and refit rear reverse sensor
- 4 To remove and refit rear garnishes and etc.
- 5 Tuff coat on affected parts
- 6 To check wiring
- 7 To remove and refit rear fender glass

\$700.00 400

\$800.00 400

\$120.00 50

na \$200.00 X

na \$100.00 X

\$80.00 20

na \$200.00 X

\$2,200.00

5244.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: