

Not Withheld
 11 Days @ 1530h
 Repairing After Rain
 3 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SNL 5332E

Acc: 24.11.24

S/N Parts Description

- 1 Taillamp RH
- 2 Rear fender RH
- 3 Rear fender glass with midg RH
- 4 Rear bumper assy
- 5 Rear bumper relector RH
- 6 Rear bumper retainer white
- 7 Rear bumper retainer black

Unit Price Amt

cr \$556.00 ✓
 n \$940.00 X
 nn \$450.60 X
 Br/cr \$595.00 ✓
 cm \$72.10 ✓
 cm \$108.20 ✓
 cm \$192.60 ✓

258

Special Nett

- 1 Rear bumper clips
- 2 Rear fender glass sealant

m \$50.00 ✓
 nn \$80.00 X

Labour

- 1 To cut/weld and remove and refit damaged parts
- 2 To spray paint on affected parts
- 3 To remove and refit rear reverse sensor
- 4 To remove and refit rear garnishes and etc.
- 5 Tuff coat on affected parts
- 6 To check wiring
- 7 To remove and refit rear fender glass

\$700.00 400
 \$800.00 400
 \$120.00 50
 n \$200.00 X
 nn \$100.00 X
 \$80.00 20
 nn \$200.00 X
 \$2,200.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: