

# 張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)  
 Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558  
 SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012  
 REG. NO. 275084 / 00X

ECICS LIMITED  
 7 Temasek Boulevard  
 #10-01 Suntec Tower One  
 Singapore 038987  
 Tel: 63374779  
 Fax: 63389267  
 Email: claims@ecics.com.sg

*not Authorized  
 Mr  
 Meras  
 27/11/24  
 HP 90096608  
 1/5 # 2200  
 take photo of the ups  
 H. J. S*

Dear Sir/Madam

26.11.2024

RE: THIRD PARTY CLAIMS FOR FBS2246X AGAINST YOUR  
 INSURED SLQ4318B , ACCIDENT ON 10.11.2024 AT  
 PUNGGOL ROAD

PG 1

DESCRIPTION	AMOUNT
1 COVER MUFFLER <i>cu7</i>	\$ 45.00 /
2 PROTECTOR MUFFLER <i>cu7</i>	\$ 165.00 /
3 FORK ASSY LH <i>Su</i>	\$ 185.00 X
4 FRONT BRAKE LEVER <i>cu7</i>	\$ 25.00 /
5 HANDLE BAR <i>hnt</i>	\$ 75.00 /
6 FRONT CENTER COVER <i>cu</i>	\$ 95.00 /
7 FRONT SIDE COVER RH <i>cu</i>	\$ 195.00 /
8 COVER FLOOR SIDE RH <i>cu</i>	\$ 98.00 /
9 STEP FLOOR RH <i>cu7</i>	\$ 75.00 /
10 COVER FLOOR SIDE LH <i>cu7</i>	\$ 98.00 /
11 STEP FLOOR LH <i>cu7</i>	\$ 75.00 /
12 FRONT FENDER <i>cu</i>	\$ 110.00 /
13 COVER OUTER AIR CLEANER <i>cu7</i>	\$ 55.00 /
14 CASE INNER AIR CLEANER <i>cu7</i>	\$ 55.00 X
15 FRONT SIGNAL RH <i>cu</i>	\$ 65.00 /
16 MIRROR RH <i>cu7</i>	\$ 35.00 /
17 CAP TAIL <i>cu</i>	\$ 35.00 /
18 COVER REAR UPPER FENDER <i>D.S</i>	\$ 40.00 /
19 BRACKET REAR FENDER <i>D.S</i>	\$ 75.00 /
20 COVER REAR FENDER LOWER <i>D.S</i>	\$ 38.00 /
21 FENDER A <i>D.S</i>	\$ 60.00 /
22 REFLECTOR <i>320</i>	\$ 20.00 /
23 REAR FENDER C <i>D.S</i>	\$ 48.00 /
24 FRONT LOWER COVER <i>cu7</i>	\$ 60.00 /

25 FRONT SIDE COVER LH (11)	\$ 195.00
26 HEAD LAMP ASSY (12)	\$ 800.00
	<hr/>
	\$ 2,822.00
Less 10%	\$ 282.20
Sub Total	<hr/> <hr/>
	\$ 2,539.80

Nett Item		
1 TRANSPORT	refer to 100	\$ 45.00 X
2 LABOUR CHARGES		\$ 280.00 250
Sub Total		<hr/> <hr/>
		\$ 325.00
Total		<hr/> <hr/>
		\$ 2,864.80


THANKS  
TSP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

2582  
P-2822  
102  
P-2539.80  
S.N-20  
+ 250  
2809.8



張 噴 漆  
**TEO SPRAY PAINTING**

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)  
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558  
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012  
REG. NO. 275084 / 00X

ECICS LIMITED  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987  
Tel: 63374779  
Fax: 63389267  
Email: claims@ecics.com.sg

Dear Sir/Madam

29.11.2024

RE: THIRD PARTY CLAIMS FOR FBS2246X AGAINST YOUR  
INSURED SLQ4318B , ACCIDENT ON 10.11.2024 AT  
PUNGGOL ROAD

Supplementary

1 STAY FRONT COVER LH	Dye	\$ 60.00 ✓
2 STAY FRONT COVER RH	Dye	\$ 60.00 ✓
3 HEADLIGHT COVER	cut	\$ 55.00 ✓
4 NUMBER PLATE LIGHT	cut	\$ 65.00 ✓
		<u>\$ 240.00</u>
	LESS 10%	<u>\$ 24.00</u>
	Sub Total	<u><u>\$ 216.00</u></u>

NETT ITEM

1 REAR NUMBER PLATE	cut	\$ 20.00 ✓
	Sub total	<u><u>\$ 20.00</u></u>
	Total	<u><u>\$ 236.00</u></u>