

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 04 Dec 2024

Preliminary Advice

Insured Vehicle No	: SLQ4318B	Accident Date	: 10/11/2024
TP Vehicle No	: FBS2246X	Assignment Date	: 27/11/2024
Make	: HONDA ADV150	Est. Duration of Repair	: 4
Date of Inspection	: 27/11/2024		
Inspection At	: TEO SPRAY PAINTING (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558 SINGAPORE 539187		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,100.80
Revised Amount	:S\$	2,809.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,809.80
Lump Sum Repair	:S\$	2,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.