



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24110566/Kqp3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	12/12/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 1017T	Veh. Inspected	SNF 5995Z
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/060	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	27/11/2024

### 2. Vehicle Details

Make & Model	TOYOTA SIENTA (A)	C.C	1490
Engine No.	M15AY786885	Year of Reg.	10/10/2023
Chassis No.	JTDBBBA340L001058	Colour	GREEN
Odometer	76526 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/65R15	DUNLOP	8
L/H Front Tyre	185/65R15	DUNLOP	8
R/H Rear Tyre	185/65R15	DUNLOP	8
L/H Rear Tyre	185/65R15	DUNLOP	8

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	22/11/2024	Inspection Date	02/12/2024
Survey held at	MASSIVE TRADING & AUTO - BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days