

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

Cheow Kok Chee
Blk 549A Swgar Road
#05-656
Singapore 671549

Vehicle No : SNF 5995 Z
Make/Model : Toyota Sienta
Year : 2022

*Not Withheld
L1 Rep @ 1000h
Putty After Paint
2 days*

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
1 pc	Rear bumper <i>720.10</i>		
1 pc	Rear o/s bumper side garnish		
1 pc	Rear o/s bumper side retainer		
1 pc	Rear o/s bumper reflector		
1 pc	Rear o/s reverse sensor		
			<i>258</i>

<i>mgent</i>	\$850.70	—
<i>DI1</i>	\$305.10	—
<i>CM</i>	\$65.70	—
<i>Sm</i>	\$155.60	X
<i>Sm</i>	\$255.70	X
	\$1,632.80	
	\$408.20	
	<u>\$1,224.60</u>	

S Nett

10 pcs Rear bumper clip

\$2.00 *na* \$20.00 ✓

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$600.00 *200l*

To putty and spray paint

\$600.00 *200l*

Check & reconnect wiring.

\$35.00 *10l*

Total \$2,479.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: