

ASS. REC. BY:

REF: LPC/Kenneth**ASSIGNMENT**

From: _____

Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MY ☒

To Inspect Vehicle No: _____

at Workshop m/s At Lim

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

100m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$128k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDV 8811KYr Regn: 04, 23Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: Toyotac.c. 1598Colour M.P. white

A/C: Insured / Std / NI / NA

Sp. Reading 30200

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 2BE 3BE 200021560Gen. Cnd: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 20/11/24D.O.I. 28/11/2024

Survey held at _____

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

) S - RS. SI



: Interview (\$ _____)

) FIDMS



: Tech Invs (\$ _____)

) Others



: Weekend (\$ _____)

)

TOTAL

Report Format :

Imp Sum / I.B.I: (\$ _____)

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN KAI MING (CHEN KAIMING)
1 NIM RISE

SINGAPORE 804420

ATTN:

Estimate No: MC1904710
Date: 26 Nov 2024
Policy No: MT/01489117
Veh Reg No: SDV8811K
Make/Model: TOYOTA COROLLA
ALTIS ELEGANCE
(AUTO)(2WD)

Your Ref No: SDV8811K
Claim Type: Third Party -> *work*
Accident Date: 20/11/2024
TP Veh Reg No: GBL8086M

LKK
10am
Not Notified
Primary Repair
2 days

Estimate Repair Cost to Vehicle No :SDV8811K

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT GRILLE ASSY	1 PC	432.60	7
2 FRONT GRILLE BASE	1 PC	261.60	7
3 FRONT BUMPER	1 PC	565.70	7
4 FRONT BUMPER CLIPS	15 PC	<i>na</i> 57.00	✓
5 FRONT BUMPER LOWER AIR GRILLE	1 PC	<i>cm</i> 511.60	✓
6 FRONT BUMPER REINFORCEMENT	1 PC	663.50	7
7 FRONT BUMPER SPONGE	1 PC	125.30	7
		2,617.30	
	Less 25%	654.33	1,962.98
Special Nett			
8 NUMBER PLATE	1 PC	<i>net</i> 35.00	✓
		35.00	35.00
LABOUR			
9 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	<i>200</i>
10 TO SPRAY FRONT BUMPER	1 PC	300.00	<i>200</i>
		600.00	600.00
		Total	S\$ 2,597.98
		Add GST @ 9%	233.82
		Total Amount Payable	S\$ 2,831.80

TOTAL: SINGAPORE DOLLAR TWO THOUSAND EIGHT HUNDRED THIRTY ONE AND CENTS EIGHTY ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE