

Kok Wang Car Grooming
1 Soon Lee Street #06-40 Pioneer Centre
Singapore 627605
Hp: 91839633 E-mail: vianong@ymail.com

ESTIMATE REPORT

Vehicle Number : SMS8436U
 Make And Model : Toyota Noah Hybrid
 Date of Accident : 21 June 2024

S/No	Parts	QTY	Unit Price	List Price
1	Front bumper	1	\$	848.30 <i>de</i>
2	Front bumper retainer RH	1	\$	132.20 <i>de 62.40</i>
3	Front bumper fog lamp cover RH	1	\$	137.70 <i>x</i>
4	Front bumper sponge	1	\$	101.60 <i>x</i>
5	Front bumper under cover RH	1	\$	165.80 <i>x</i>
6	Front fender RH	1	\$	1,425.10 <i>bf 850</i>
7	Front fender bracket RH	1	\$	60.50 <i>x</i>
8	Front fender inner shield RH	1	\$	232.80 <i>x</i>
9	Front fender 'HYBRID' emblem RH	1	\$	81.50 <i>rec 54.60</i>
10	Front rim RH	1	\$	2,327.00 <i>x</i>
11	Wing mirror assy RH	1	\$	1,632.40 <i>x</i>
12	Wing mirror cover RH	1	\$	131.90 <i>x</i>
13	Headlamp RH	1	\$	4,609.90 <i>can</i>
				\$ 11,886.70 <i>3250</i>
Less 25%				\$ 2,971.68 <i>5070.30</i>
Total				\$ 8,915.03 <i>3802.72</i>
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company				
Special Nett Item 1 Front bumper clips 2 Front fender inner shield clips RH Acknowledged by Repairer Signature: _____ Date: _____ 1 set 1 set				
				\$ 60.00 <i>4000</i>
				\$ 60.00 <i>x 11</i>
Total				\$ 120.00 <i>40</i>

Labour & Misc Charges

To dismantle, replace & panel beating affected portion.	\$	800.00 <i>500</i>
To spray paint on affected portion.	\$	800.00 <i>800</i>
To check wiring.	\$	60.00 <i>30</i>
To apply anti-rust on affected areas.	\$	80.00 <i>30</i>
To conduct computerized wheel alignment.	\$	150.00 <i>x 11</i>
To perform system diagnostic & reset ECU system.	\$	300.00 <i>x 11</i>
Total	\$	2,190.00 <i>1360</i>

Grand Total : \$ 11,225.03

Taufik 97495749
wf 12/7/24 e 11 am
115 Resurvey after repair
4 days
Taufik c/hh auto. l.m.

3802.72
40
1360
5202.72
115 x 4150, 4 days \$