

YEW TEE AUTOMOBILE TECH PTE LTD

39 WOODLANDS CLOSE #01-12 MEGA@WOODLANDS S(737856)
25 KAKI BUKIT ROAD 4 #01-61 SYNERGY@KB S(417800)

To: GREAT AMERICAN INSURANCE COMPANY

DATE: 28.11.2024

Dear Sir / Madam:

RE: VEHICLE REPAIR ESTIMATE

Owner : YEN LONG TRANSPORT SERVICE

Model : TOYOTA HIACE

Reg : GBF5704P Chassis: KDH2010207920 DOAccident : 25.11.2024

OWN DAMAGE CLAIM AGAINST

We are please to submit our estimate of repairs to the above mention vehicle.

	Parts	Labour
1 BONNET / M	\$ 400.00	
2 BONNET HINGE RH X	\$ 100.00	
3 BONNET HINGE LH X	\$ 100.00	
4 BONNET LOGO / MC	\$ 90.00	
5 FRONT CORNER PANEL LH X	\$ 140.00	
6 FRONT HEADLAMP LH / BR	\$ 1,800.00	
7 FRONT GRILLE BASE / BR	\$ 480.00	
8 FRT GRILLE OUTER BLACK GARNISH / BR	\$ 300.00	
9 FRONT GRILLE TOP CHROME / CVT	\$ 250.00	
10 FRT GRILLE MID CHROME / CVT	\$ 250.00	
11 FRT GRILLE LOWER CHROME / CVT	\$ 250.00	
12 FRONT BUMPER GRILLE / BR	\$ 100.00	
13 FRONT BUMPER / BR	\$ 320.00	
14 FRONT BUMPER SIDE RETAINER LH / BR	\$ 115.00	
15 FRT BUMPER REINFORCEMENT / BT	\$ 300.00	
16 FRT BUMPER REINFORCEMENT LOWER / BT	\$ 220.00	
17 AIR CON CONDENSER X	\$ 480.00	
18 AIR CON CONDENSER SIDE GARNISH LH X	\$ 90.00	
19 HORN LH X	\$ 80.00	
20 FRONT DOOR LH X	RPR	
21 FRONT DOOR TOP HINGES LH X	RPR	
22 WASHER TANK / CR4	\$ 140.00	

Total Parts : \$ 6,005.00
10% \$ 600.50
\$ 6,605.50

23 FRONT BUMPER CLIPS (SET) / MC	S/NETT	\$ 35.00	30
24 FRONT NUMPER PLATE / BR	S/NETT	\$ 45.00	
25 CHECK WIRING / MC	NETT	\$ 50.00	30
26 TOP UP GAS / X	NETT	\$ 45.00	
27 To remove, refix, realign, adjust and replace all damaged parts.		\$ 400.00	/
28 To respray paint of accident section.		\$ 600.00	300
Labour Total :		\$ 1,175.00	

Grand Total :

\$ 7,780.50

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

Shaun : 97432262

Site (LKK)

28/11/24, 3:00 pm

OB - M AL

EXCISE - ?

L/H

M AL M
4 djs