



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS GREAT AMERICAN INSURANCE COMPANY	Ref:	CS/GAI24110570/Evp3m4
3 TEMASEK AVENUE	Date:	09/12/2024
#16-01 CENTENNIAL TOWER	Code:	GAI
SINGAPORE 039190		

### 1. Policy Particulars :- OWN DAMAGE CLAIM

Insured Veh.	-	Veh. Inspected	GBF 5704P
Policy No.	MOMVC000008825-03-000	Coverage	0
Claim No.	CLMOMVC000004569	Excess	\$600.00
Assign From	JOCELYN	Assign Date	26/11/2024

### 2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KD2657003	Year of Reg.	19/12/2016
Chassis No.	KDH2010207920	Colour	SILVER
Odometer	125691 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15C	BRIDGESTONE	5
L/H Front Tyre	195R15C	BRIDGESTONE	5
R/H Rear Tyre	195R15C	BRIDGESTONE	5
L/H Rear Tyre	195R15C	BRIDGESTONE	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	25/11/2024	Inspection Date	28/11/2024
Survey held at	YEW TEE AUTOMOBILE TECH PL BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

### 5a. Remarks

A)THE MARKET VALUE IS S\$35,000.00(EST. AVERAGE)  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days