

ASS. REC. BY:

REF:

1662/

CS/FCI 24110571/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$3K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

01/25

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBB 7652M

Yr Regn: 02.10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M/S Urban

C.C. 2953

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

281746

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1M64E2580793174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15 XP

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

21/11/24

D.O.A.

22/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1) Wkip and owner will renew COE Perm.

24/12/12 @ 2100. Carhit (Red, \$5291.42, 71%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

S - RS. \$

: Extras

: Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE GBB7652M

Not Authorized
C/Sing 82100k Max

Presumy After Pairs
5 days

No. Qty Nett Items

<u>Nett Items</u>		
1	1	Rear RH body panel sliding door rail
2	1	Rear RH wheel rim
3	1	Rear RH wheel hub
4	1	Rear RH wheel bearing
5	1	RH sliding door
6	1	RH sliding door outer handle
7	1	RH sliding door lower roller
8	1	RH sliding door lower roller bracket
9	1	RH sliding door centre roller
10	1	RH sliding door top roller
11	1	RH sliding door lower release lock
12	1	RH sliding door rubber
13	1	RH sliding door switch
14	1	RH sliding door inner board
15	1	RH sliding door inner board clips
16	1	RH sliding door rear inner lock
17	1	RH sliding door rear inner lock catch
18	1	RH sliding door inner central lock assy

\$	Ad/Ln	421.90	✓
\$	R	225.10	X
\$	Ln	383.40	Z
\$	Ln	129.30	X
\$	R	1,237.80	✓
\$	Ln	196.10	X
\$	R	195.00	X
\$	R	159.60	X
\$	Dis	184.40	✓
\$	R	122.20	X
\$	Ln	187.70	X
\$	Ln	175.00	87.50in
\$	Ln	157.20	X
\$	CM	518.80	✓
\$	Ln	60.00	✓
\$	Dis	303.40	✓
\$	R	81.90	X
\$	Ad	385.00	✓
\$		5,123.80	
Less 10%	\$	512.38	
Total :	\$	4,611.42	

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,000.00	500
2	To putty and spray Spray Paintings charges.	\$	1,400.00	700
3	To remove, transfer & replace RH sliding door fittings.	\$	100.00	60
4	To remove, refit rear RH under carriage damage parts.	\$	100.00	X
5	To conduct computerise wheel alignment test.	\$	100.00	60
6	To apply anti rust treatment	\$	80.00	30
Total :	\$	2,780.00		

Total Parts and Labour : \$ 7,391.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: