



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDV9099T

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
6 RAFFLES QUAY
#21-00
SINGAPORE 048580
65073848

Vehicle & Document Information
WIP No 22440
Reg No/Reg Date SDV9099T / 14/09/2021
Date In/Mileage 29/11/2024/ 54328
Chassis No W1N2539802F9798136
Engine No 26492030425912
Make/Model MB/GLC 200
Colour/Trim 021 197 Obsidian Bl/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator					
WF001862	Credit	15/02/2025/ 11:50	CH	371 / Go Chee Han					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : MPC24P00320400 // 26-11-2024									
DRIVE IN/EXCESS : 26-11-2024 // SHA1201E - FIRST CAPITAL									
DATE IN/DATE SURVEY: 29-11-2024 // RASUL - LKK									
DIRECT SETTLEMENT BY: 27-11-2024 // CHRIS LIM - FIRST CAPITAL									
A BPILAB								960.00	
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.							0.05	800.00	
A BPIRES									
RESpray REAR BUMPER							0.10	380.00	
A BPILAB									
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT								120.00	
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT								540.00	
A BPILAB									
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								60.00	
S BPNSUB									
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM,(RUN FLAT)									
WHEEL BALANCE AND INSTALL NEW VALVE HEAD								15.00	
M BPNSUN									
SUNDRIES									
X REAR BUMPER LOWER BLACK TRIM					1.00	588.09	00.00	588.09	
X RH/REAR FENDER BLACK TRIM					1.00	320.29	00.00	320.29	
X RH/REAR DISK WHEEL					1.00	966.89	00.00	966.89	
X REAR BUMPER					1.00	1092.38	00.00	1092.38	

Confirmed & accepted by

9% GST on **5842.65** **525.84**

Total Payable 6,368.49

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG