



26/11/2024

VEHICLE REGISTRATION NO.: SND8247R
VEHICLE MAKE/MODEL: TOYOTA / ESQUIRE
CHASSIS NUMBER: ZWR800481767
CONTACT PERSON :

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER PLATE LAMP	2	\$ 78.90	\$ 157.80
2	REAR BUMPER	1	\$ 1,180.90	\$ 1,180.90
3	REAR BUMPER SIDE HOLDER	RHX ^{mm} 2	\$ 70.90	\$ 141.80
4	REAR BUMPER TOW COVER	1	\$ 28.10	\$ 28.10
5	REAR BUMPER REFLECTOR	RHX ^{mm} 2	\$ 85.90	\$ 171.80
6	REAR END PANEL	1	\$ 735.70	\$ 735.70
7	REAR END PANEL TOP GARNISH	1	\$ 148.60	\$ 148.60
8	REAR END PANEL ANTENNA SENSOR	1	\$ 184.60	\$ 184.60
9	TAILLAMP	2	\$ 685.10	\$ 1,370.20
10	TAILLAMP OUTER PANEL	2	\$ 311.10	\$ 622.20
11	TAILLAMP LOWER APRON	2	\$ 178.80	\$ 357.60
12	TAILGATE	1	\$ 1,958.90	\$ 1,958.90
13	TAILGATE LOCK	1	\$ 398.90	\$ 398.90
14	TAILGATE LOWER LOCK CATCH	1	\$ 38.90	\$ 38.90
15	TAILGATE WEATHERSTRIPE	1	\$ 375.10	\$ 375.10
16	TAILGATE OUTER MOULDING	1	\$ 581.50	\$ 581.50
17	TAILGATE INNER TRIM BOARD	1	\$ 761.80	\$ 761.80
18	TAILGATE DAMPER	2	\$ 326.80	\$ 653.60
19	TAILGATE HINGE	2	\$ 113.40	\$ 226.80
20	TAILAGTE SIDE GARNISH	2	\$ 396.90	\$ 793.80
21	TAILGATE GLASS MOULDING	1	\$ 420.00	\$ 420.00
22	TOYOTA LOGO	1	\$ 78.20	\$ 78.20
23	HYBRID EMBLEM	1	\$ 58.40	\$ 58.40
24	REAR FENDER INNER TRIM BOARD	2	\$ 906.50	\$ 1,813.00
25	REAR FENDER INNER SHIELD	2	\$ 125.90	\$ 251.80
26	JACK COVER	1	\$ 128.70	\$ 128.70
27	FLOOR PANEL	1	\$ 980.80	\$ 980.80
28	FLOOR PANEL TOP BOARD	1	\$ 950.60	\$ 950.60
29	FLOOR PANEL MAT	1	\$ 582.40	\$ 582.40
30	REAR EXHAUST PIPE	1	\$ 892.50	\$ 892.50
31	REAR EXHAUST PIPE MOUNTING	1	\$ 38.90	\$ 38.90
32	REAR EXHAUST PIPE GASKET	1	\$ 35.20	\$ 35.20
33	REAR EXHAUST PIPE HEAT SHIELD	1	\$ 188.20	\$ 188.20

5974.40
4480.80

	ITEMS	QTY	UNIT PRICE	TOTAL
--	-------	-----	------------	-------

1	REAR NUMBER PLATE	1	\$	30.00	\$	30.00	X nn
2	REAR NUMBER PLATE HOLDER	1	\$	30.00	\$	30.00	X nn
3	REAR BUMPER CLIPS	1 SET	\$	30.00	\$	30.00	nel
4	REAR END PANEL TOP GARNISH CLIPS	1 SET	\$	20.00	\$	20.00	nel
5	REAR END PANEL SEALANT	1	\$	60.00	\$	60.00	4-0nel
6	TAILLAMP LOWER APRON CLIPS	2 SET	\$	20.00	\$	40.00	X nn
7	TAILGATE INNER TRIM BOARD CLIPS	1 SET	\$	30.00	\$	30.00	nel
8	TAILGATE GLASS SEALANT	1	\$	60.00	\$	60.00	nel
9	TAILGATE STICKER	1	\$	30.00	\$	30.00	nel
10	REAR CAMERA	1	\$	450.00	\$	450.00	X
11	REAR VIDEO CAMERA	1	\$	580.00	\$	580.00	X
12	REAR FENDER INNER TRIM BOARD CLIPS	2 SET	\$	30.00	\$	60.00	X
13	REAR FENDR INNER SHIELD CLIPS	2 SET	\$	30.00	\$	60.00	X
14	FLOOR PANEL SEALANT	1	\$	60.00	\$	60.00	X
TOTAL :					\$	1,540.00	210

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,600.00	700	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	700	
3	WIRING CHECK	\$ 100.00	30	
4	TO APPLY TUFF COAT	\$ 200.00	30	
5	TO REMOVE REAR UPHOLSTERY & REAR LH & RH SEATS	\$ 380.00	60	
6	TO REMOVE REAR CAMERA	\$ 100.00	30	
7	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	X nn	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120	
10	TO REMOVE EXHAUST PIPE	\$ 150.00	X nn	
TOTAL:		\$ 4,560.00		

ESTIMATE REPORT

TOTAL PARTS COST:	\$	14,520.48
TOTAL LABOUR COST:	\$	4,560.00
TOTAL REPAIR COST:	\$	19,080.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfikh 97495749/62563561
w/p 27/11/240 130pm
L/S Resurvey after repair
tanfikh@lkhauto.com.
6 days

4480.80
210
1750
6420.80
L/S \$5100, 6 days #