

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

YEO AH LENG
BLK 210 BOON LAY PLACE #03-113
SINGAPORE 640210

Contact : 97562152

Xiao Tony

TAX INVOICE

Repair Code : CLM16492
Date in : 26/11/2024
Vehicle Num. : SNN4920D
Model : HONDA VEZEL 1.5G CVT
Chassis/Eng# : RV31005777/L15Z1006730

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE <i>Best</i>	1	1407.70	✓ 1,407.70
REAR RH BEARING WITH SENSOR <i>Repa</i>	1	397.60	✓ 397.60
REAR RH FENDER ARCH GARNISH <i>at</i>	1	201.50	✓ 201.50
REAR RH FENDER INNER SHIELD COVER <i>Rea</i>	1	197.50	✗ 197.50
REAR RH SHOCK ABSORBER <i>new</i>	1	475.60	✗ 475.60
REAR RH SPORT RIM <i>at</i>	1	975.20	480 (sw) 975.20
Subtotal before discount			3,655.10
Percentage discount 20%			731.02
Sub-total 1			2,924.08
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	30.00	20 30.00
REAR RH FENDER INNER SHIELD COVER CLIPS - SET <i>new</i>	1	30.00	20 + 30.00
REAR RH TYRE <i>new</i>	1	380.00	✗ 380.00
Subtotal before discount			440.00
Percentage discount 0%			0.00
Sub-total 2			440.00
Parts-total			3,364.08

LABOUR

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

50 450.00
80 100.00

*** This is a computer-generated document which requires no signature.***

oki Bukit AutoHub
2 oki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

YEO AH LENG
BLK 210 BOON LAY PLACE #03-113
SINGAPORE 640210

Contact : 97562152

TAX INVOICE

Repair Code : CLM16492

Date in : 26/11/2024

Vehicle Num. : SNN4920D

Model : HONDA VEZEL 1.5G CVT

Chassis/Eng# : RV31005777/L15Z1006730

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,010.00
Parts & Labour Total	4,374.08

*** This is a computer-generated document which requires no signature.***

page 2

Adrian Cj
L/s 27/11/24.
03 days.

total: 2585.44.
L/s: 2K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: