

TP INC
 Hui Pong

Vehicle Number : SMH9062R
 Vehicle Model : TOYOTA VIOS
 Accident Date : 24.11.2024
 Original Reg Date : 15.02.2019

Date : 27.11.2024
 Chassis : MR2B23F3201164956

ESTIMATE

1	1 pc	Boot Lid <i>Dented</i>		980.00	✓
2	2 pc	Boot Lid lamps <i>New</i>	465.90	931.80	+
3	2 pc	Boot Lid lamps inner sealer <i>New</i>	38.00	76.00	+
4	2 set	Boot Lid lamps clips <i>New</i>	30.00	60.00	+
5	1 pc	Boot Lid Badge <i>New</i>		95.60	✓
6	1 pc	Boot Lid Emblem (Vios) <i>New</i>		93.70	✓
7	1 pc	Boot Lid Emblem (E) <i>New</i>		92.30	✓
8	1 pc	Boot Lid Insulator <i>New</i>		345.80	+
9	1 set	Boot Lid Insulator Clip <i>New</i>		30.00	+
10	1 pc	Boot Lid Inner Lock <i>New</i>		398.50	+
11	1 pc	Boot Lid Lock Catch <i>New</i>		48.60	+
12	1 pc	Boot Lid Weatherstrip <i>At</i>		198.50	✓
13	1 pc	Rear Bumper <i>Distorted</i>		<u>885.40</u>	625
14	2 pcs	Rear Bumper Side Retainers <i>New</i>	186.30	372.60	+
15	1 set	Rear Bumper Clips <i>New</i>		50.00	30
16	1 pc	Rear Bumper Reinforcement <i>Dented</i>		<u>862.80</u>	415
17	2 pc	Rear Bumper Reinforcement brackets <i>RH Dented</i>	286.90	573.80	286.80
18	2 pcs	Rear Bumper Reflectors <i>RH Missing</i>	215.20	430.40	215.20
19	2 pcs	Rear Bumper Reverse Sensor <i>1 piece missing</i>	286.00	572.00	286
20	2 pcs	Rear Bumper Reverse Sensor Holder <i>New</i>	52.00	104.00	+
20	1 pcs	Rear Bumper Reverse Wiring Harness <i>New</i>		433.20	+
21	1 pc	End Panel <i>Dented</i>		775.80	✓
22	1 pc	End Panel Top Trim <i>Dented</i>		288.90	✓
23	1 set	End Panel Top Trim Clips <i>New</i>		30.00	10
23	1 pc	Taillamp Panel <i>Repair</i>	456.20	912.40	+
24	1 pc	Spare Tyre Panel <i>Repair</i>		725.90	+
25	1 pc	Spare Tyre Panel Top Board <i>torn</i>		<u>466.80</u>	325
26	2 pcs	Spare Tyre Panel Top Side Sponge <i>RH torn</i>	312.00	624.00	<u>312</u> 195
27	1 pc	Spare Tyre Wheel Nut <i>New</i>		49.20	+
27	1 pc	Smart Key Sensor <i>New</i>		245.20	+
28	1 pcs	Rear Exhaust Muffler <i>Dented</i>		<u>985.60</u>	685
29	1 pcs	Rear Exhaust Muffler Holder rubber <i>torn</i>	87.50	175.00	45
30	1 pcs	Rear Exhaust bracket <i>New</i>		204.50	+
31	1 pcs	Rear Fender <i>Repair</i>	897.60	897.60	+

32	1 pcs	Rear Fender Inner Trim <i>the m</i>	414.80	414.80	+
33	1 set	Rear Fender Inner Trim Clips <i>the m</i>	30.00	30.00	+
34	1 pcs	Rear Fender Inner cowling <i>missing</i>	185.60	185.60	✓
35	1 set	Rear Fender Inner cowling set <i>the m</i>	30.00	30.00	✓
35	2 pcs	Rear Fender Side Garnish <i>the m</i>	125.60	251.20	+
36	2 pcs	Taillamps <i>RT cracked</i>	538.50	1,077.00	538.50
37	2 pcs	Taillamps lower brackets <i>RT cracked</i>	89.80	89.80	49.90
38	1 pcs	Taillamps Inner Sealer <i>the m</i>	38.00	38.00	+
39	1set	Taillamps Clips <i>not m</i>	25.00	25.00	+
			subtotal	16,157.40	
			Less 25%	4,039.35	
			total	12,118.05	

6451.90
4838.92

Special Nett

1	1 set	Body Panel Joint Sealant <i>the m</i>		120.00	60
2	1 set	Windscreen sealant <i>the m</i>		80.00	+
3	1 pc	Rear Number Plate <i>the m</i>		50.00	+

Labour Charge

Panel Beating		2,000.00	1000
Spray painting		2,000.00	1000
Check Wiring on tailamps		120.00	30
Anti rust		120.00	60
Remove and install bootlid <i>fitting</i>		180.00	60
Remove and install fuel tank		100.00	+
Remove and install carpet and seat.		120.00	60
Remove and install reverse sensor		120.00	50
Remove and install rear exhaust silencer.		250.00	80
		\$ 17,378.05	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2340

Adnan

4/s 27/11/24

07 Days

total: 7238.92

4/s: 5.8k

5.8k