

ASS. REC. BY:

Tajjith

REF:

CO/11/24/110579/TP43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

47800

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seent _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum. Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBH 9130H Yr Regn: 2013/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha YZ16 c.c. 153

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ME14550BLD2010302

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: MD / S/Rim / STD A/Rim or

Tyre Size: F: 100/80R17

R: 140/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 28/11/24

Survey held at Pang Seater

Des. of Damages: FR / RR / OS / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

PANG SCOOTER SERVICE

Bik 1006 Bukit Merah Lane 2 #01-06 Singapore 159762
Tel : 6271 4618 Email: pang_s_s_m@slhgnet.com.sg

ESTIMATE REPAIR

BIKE NO.: FBH9130H

DOA : 22/11/2024

MAKE/MODEL : YAMAHA FZ16

S/No	DESCRIPTION	AMOUNT
1	HANDLE BAR	\$ bt 85.00
2	R/H HANDLE BRACKET END	\$ wt 25.00
3	R/H MIRROR	\$ mis 45.00
4	UNDER BRACKET	\$ bt 230.00
5	STEERING CONE (1 SET)	\$ rec 120.00
6	FORK INNER TUBE (x 2)	\$ bt 460.00
7	FORK OIL (x 2)	\$ rec 80.00
8	F BRAKE DISC	\$ bt 195.00
9	F WHEEL RIM	\$ bt 398.00
10	F WHEEL SHAFT	\$ bt 48.00
11	MUFFLER ASSEMBLY	\$ del 680.00
12	MUFFLER GASKET	\$ rec 25.00
13	L/H TAIL COVER	\$ cu 130.00
14	R/H TAIL COVER	\$ cu 130.00
15	CENTER TAIL COVER	\$ mis 50.00
16	TOP REAR COVER FENDER	\$ cu 98.00
17	REAR FENDER	\$ cu 98.00
18	(N) PLATE FENDER	\$ nnx 65.00
19	CHAIN GUARD	\$ nnx 85.00
20	SWIM ARM ASSEMBLY	\$ bt 390.00
21	SWIM ARM BUSH KIT (1 SET)	\$ dis 150.00
22	SWIM SHAFT	\$ bt 45.00
23	REAR WHEEL SHAFT	\$ bt 48.00
24	REAR WHEEL RIM	\$ bt 398.00
25	WHEEL BEARING	\$ dis 80.00
26	TAIL LIGHT ASSEMBLY	\$ cu 98.00
27	REAR (N) PLATE	\$ bt 25.00
28	PRESS BODY FRAME	\$ Dis 350.00
29	LABOUR	\$ 200 500.00
Total :		\$ 5,131.00

Temp: 3-4 days.
Tangin 92495749
up: 28/11/24 2400pm
tangin clh auto car

4131
10%
3717.90

300

500

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

SUPPLEMENTARY ESTIMATE REPAIR

BIKE NO.: FBH9130H

DOA : 22/11/2024

MAKE/MODEL : YAMAHA FZ16

S/No	DESCRIPTION	AMOUNT
1	REAR SEAT ASSEMBLY	\$ ht 150.00
		150
		107, 135
		3717.90
		5 00
		135
		4352.90
		4583450
		5 days
Let Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Part prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
Acknowledged by Repairer: Signature: _____ Date: _____		
Total :		\$ 150.00