

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : D24010358MFCT Date: 09th December 2024

Our Ref : CS/FCI24110581/Kqp3m4

M/s MS First Capital Insurance Ltd

16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKQ 7866C INSURED VEHICLE: SHA 1559Z ACCIDENT ON 22/11/2024

Instruction was received to inspect the vehicle Reg. No. SKQ 7866C. The inspection was conducted on 27/11/2024 at Blk 1 Sin Ming Industrial Estate Sector C, #01-135, Singapore 575636 Repairer: M/s Auburn Auto Pte Ltd

The following vehicle information was recorded:

Registration Number : SKQ 7866C

Make/Model : Volkswagen Golf A7 1.4 TSI AT 5G13GZ W/O HID

Year of Registration : 2014

Body Colour : Metallic Silver

Chassis Number : WVWZZZAUZFW063882

Engine Capacity : 1395 cc Speedometer Reading : 222323 km

The vehicle sustained damages at the rear portion. The Estimated repair cost of such vehicle is \$\$3,207.28 (Sin Dollars: Three Thousand Two Hundred And Seven And Cents Twenty Eight Only.) (Exclude check items \$\$916.64Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "**Total Loss**".

| (a) If the vehicle to be "Total Loss" | | | | |
|--|---------|-----------|-------|-----------|
| Market Value | S\$ | 3,800.00 | (est) | |
| Less: LTA Reimbursement Value (RV) | (S\$ | 2,901.00) | | |
| Nett Liability | S\$ | 899.00 | | |
| (b) If the vehicle to be "Repair" | | | S\$ | 899.00 |
| Repair Cost (Est) (Exclude check items S\$916.64Nett) | S\$ | 3,207.28 | | |
| Nett Liability | | | S\$ | 3,207.28 |
| (a) - (b) = | | | (S\$ | 2,308.28) |
| | | | ==== | ======= |

The amount of estimated saving of S\$2,308.28 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.