

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Siew Kam Wah (87880827)

Accident Date : 22-Nov-24

Vehicle No : FBR3377A (COE: 270420-260430)

Vehicle Model : Yamaha T150

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
2	Front fork tube assy	\$ 17 640.00 X
1	Fork under bracket	\$ 17 225.00 X
1	Handle-bar	160 \$ 314 185.00 ✓
1	Hand grip (1 set)	\$ 11 95.00 X
1	Handle bar ends	40 \$ 127 128.00 ✓
2	Side mirrors	70 o/s \$ 140 140.00 1pc
1	Front pilot light	\$ 385 385.00 X
2	Front signals	160 o/s \$ 160 160.00 1pc
1	Front signal lower garnish	\$ 135 135.00 ✓
1	Front inner cover	\$ 11 180.00 X
1	Fairing assy (1 set)	680 cur \$ 725 725.00 ✓
1	Front footrest brackets	\$ 285 285.00 X
1	Front footrest o/s	160 \$ 125 125.00 ✓
1	Brake pedal	115 \$ 145 145.00 ✓
2	Rear footrest	\$ 120 120.00 X
1	Rear footrest bracket	\$ 320 320.00 X
1	Exhaust assy	\$ 625 625.00 ✓
1	Exhaust protector	\$ 125 125.00 ✓
1	Exhaust protector end cap	60 \$ 115 115.00 ✓
1	Rear fender - 1	\$ 135 135.00 ✓
1	Rear fender - 2	\$ 115 115.00 ✓
2	Rear fender bracket	\$ 220 220.00 X
1	Rear signal	\$ 11 180.00 X
1	Rear number plate lamp	110 \$ 130 130.00 ✓
1	Rear Rim	\$ 550 550.00 X
1	Rear rim shaft	\$ 128 128.00 X
1	Swing arm	\$ 680 680.00 X
1	Swing arm bush	\$ 220 220.00 X
1	Swing arm shaft	\$ 138 138.00 X
		\$ 7,354.00
Less 10%		\$ 735.40
		\$ 6,618.60

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Email: erofia@singnet.com.sg

Name : Siew Kam Wah (87880827)

Accident Date : 22-Nov-24

Vehicle No : FBR3377A (COE: 270420-260430)

Vehicle Model : Yamaha T150

Estimated Repair Costs

Special Nett Items

1	Reel Number plate (1 set)	\$	Surf	38.00	20
2	Fork oils	\$	^ ^	30.00	X
2	Fork oil seals	\$	^ ^	56.00	X
1	Steering cone (1 set)	\$	^ ^	95.00	X
1	Rear box	\$	cut	480.00	350
1	Rear box bracket	\$	Surf	180.00	120
1	Sticket (1 set)	\$	re	95.00	60
		\$		974.00	

S/No. Labour

1	To provide towing service (LOD) S\$60.00	refer to 200	\$	-	X
2	To check wiring and reset headlamp focusing		\$	^ ^	80.00 X
3	To realign body frame		\$	^ ^	420.00 X
4	To provide labour		\$		480.00 300
			\$	980.00	

Grand Total

\$ 8,572.60

Singapore Dollars: Eight Thousand Five Hundred Seventy-Two and Cents: Sixty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-2530
102
2277.00
550
300
3127
212
2801