LKK Auto Consultants #01-25 Paya Ubi Industrial Park, 51 Ubi Avenue 1

408933

Insurer Reference: SNJ929C Full Report

Repairer Reference: CM297/SNJ929C Registration: SNJ929C Date calculated: 24/01/2025 11:27 AM Printed: 24/01/2025 11:27 AM

Summary Information

Claim

Location: Singapore (SG) Work Provider: Income Insurance Limited

Printed by: KK LAU Currency: SGD Claim Reference: SNJ929C Date of Incident: 22/11/24

Estimated Repair Time: 14 Hire Car Start: Actual Repair Days: Hire Car End:

DYNAMIC SELECT

Vehicle Details

Vehicle

Manufacturer: MERCEDES-BENZ

Model: CLA (C118)
Sub Model: CLA 200
Model Sheet Number: 03 L7 44
Registration: SNJ929C

VIN number: WDD1183872N018864

Odometer: **Model Specs**

FR PRODUCTION START

INNER HEADLINING SPORT S-WHEEL LEATH AIR CON THERMATIC CRUISE CONTROL HEADUNIT ASIA

MEDIA DISPLAY H-LAMP LED HIGH PER

FOLDING REAR SEAT PROGRESSIVE
SILL MLDG ILLUMINAT OUT/IN MIRR AUTO DIM

PASS SEAT MEMORY LUMBAR SUPPORT
SEAT COMFORT PACKAGE ADVANTAGE PACKAGE

ACTIVE CARBON FILTER KEYLESS GO

7-SPEED AUTOMATIC SHIFT PADDLE ON STRG

WHEELS 7.5J X 18 ALU HANDS-FREE ACCESS PEDESTRIAN PROTECT PARKTRONIC

PARK PACK SOCKET 12V

ILLUMINAT AMBIENTE MODEL 2020

ERM BRAKE ASSIST CONNECT 20 MID LIGHT-/VIEW PACKAGE DOUBLE CUP HOLDER

S/BELT W/WARNING DEV MIRROR PACKAGE SUN VISOR SPEC FUNC

O LOAD COMPART PACKAG DLE ON STRG COMFORT SUSPENSION

HANDS-FREE ACCESS TYRE W/FLAT RUNNING PARKTRONIC COMPRESSOR VARIABLE

SOCKET 12V CLEAR COAT HARD

KNEE AIRBAG

DR MIRROR GPS AERIAL TRIM CARBON LOOK DIGITAL INSTRUMENTS LEATHER PAD ARTICO ELEC FOLD DR MIRRORS

DRIVER SEAT MEMORY

STORAGE BOX

SUN VISOR SPEC FUNC REARVIEW CAMERA
LOAD COMPART PACKAGE TYRE PRESSURE SENSOR
COMPORT SUSPENSION TYPES 225/45 P.18 W

TYRES 225/45 R18..W WIRELESS CHARGER

REAR ARMREST BASECOAT CLEAR Insurer Reference: SNJ929C **Full Report** Repairer Reference: CM297/SNJ929C Registration: SNJ929C Printed: 24/01/2025 11:27 AM

Date calculated: 24/01/2025 11:27 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All	
Underbody	



Labour

	Time Ba	se 10 WU/h	Price = 42	.00 SGD/h
Code	Description		WU	Price SGD
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNE DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	CT STAR	3.0	12.60
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC SOCKET CONNECTIONS)	PLUG AND	2.0	8.40
61-1086 01	R + R COMPL LWR ENGINE COMPAR	RTMENT COVER	5.0	21.00
61-1116 01	R + R L/UNDERFLOOR COVER		4.0	16.80
61-1117 01	R + R R/UNDERFLOOR COVER		4.0	16.80
88-1102 01	R + R FRONT BUMPER CPL		9.0	
88-1319 01	ADD FOR R + R FRONT BUMPER (VEHICLE WITH PARKTRONIC)		1.0	
88-1935 01	ADDITION TO R + R FRONT BUMPE (VEHICLE WITH PEDESTRIAN PROT		1.0	4.20
88-1933 01	ADDITION TO R + R FRONT BUMPE (VEHICLE WITH COLLISION WARN)		1.0	4.20
82-4730 01)	R + R BOTH HEADLAMPS	,	3.0	12.60
01-2800 04)	R + R ENGINE WITH GEARBOX (FRONT MODULE AND AXLE SHAFTS INCLUDES: RADIATOR, INTERCOOL ENGINE AIR DUCT, ENGINE COVER R + R AIR FILTER CPL	ER,	26.0	109.20
27-2112 01	DETACH + REFIT GEARBOX (ENGINE AND GEARBOX REMOVED)		8.0	33.60
27-2152 ZAX	RENEW AUTOMATIC GEARBOX (REN		4.0	16.80
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN EXHAUST, REFILL, PRESSURE TEST	I FLUID,	6.0	25.20
Audatex Syster	n Using Manufacturer Times	Page 2 of 4	PRINT DATE	24/01/2025

Insurer Reference: SNJ929C Full Report
Repairer Reference: CM297/SNJ929C
Date calculated: 24/01/2025 11:27 AM
Printed: 24/01/2025 11:27 AM

Code	Description			wu	Price SGD
54-2290 ZAX 82-1120 01 0283	(FOR ALL WORK ON THE SYSTEM) CALIBRATE FRONT RADAR ADJUST LED HEADLAMP FRONT BUMPER TRIM REPAIR			2.0 7.0 15.0*	8.40 29.40 63.00
	Labour Cost Panel / Mechanical Labour		Hrs 10.10	WU 101.0	424.20
	Total of Labour				424.20
Paint					
Paint Work	SYSTEM AZT		Tir	ne Basis	10 WU/h
Code	Description - BASECOAT CLEAR			WU	Price SGD
	FRONT BUMPER TRIM REPAIR PAINT PLASTIC			17.0	
Paint Material	Per Part				
Code	Description				Price SGD
0283	FRONT BUMPER TRIM REPAIR PAINT PLASTIC	:			55.49
	Labour Cost - Paint		Hrs	wu	Price SGD
	Factor Time Paint	42.00 SGD/h		17.0	
	Preparation Comp. Work Plastic		2.10	21.0	88.20
	Total	10 WU/h	3.80	38.0	159.60
	Material Cost - Paint Repair Painting Plastic Material-constant Plastic Total				Price SGD 55.49 18.10 73.59

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01 Price SGD
1003 8780 8779 8852 4283 4284	CENTER REAR COVER FRONT CENTRE TRIM FRONT GRILLE PANEL GEARBOX EXCH L/F LWR FLOOR COVER R/F LWR FLOOR COVER	247 684 0018 247 520 2600 118 885 4600 700 370 3500 80 177 680 8403 177 680 8603	Original Original Original Original Original Original	260.00 350.00 350.00 12,000.00 250.00 250.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Total			0.00 13,460.00 13,460.00

Extras

Insurer Reference: SNJ929C Full Report
Repairer Reference: CM297/SNJ929C
Date calculated: 24/01/2025 11:27 AM
Printed: 24/01/2025 11:27 AM

Code	Description	Price SGD
1001	AUTO FLUID	350.00*
1002	CALIBRATION GEARBOX	400.00*
	Total Extras	750.00

Final Calculation

	SGD	SGD
	342	565
Parts	13,460.00	
Total Parts		13,460.00
Labour Time Base 10 WU/h		
Total 101.0 WU X 42.00 SGD/h	424.20	
Total of Labour		424.20
Total Of Extras		750.00
Paint Work Time Base 10 WU/h		
Labour Cost 38.0 WU X 42.00 SGD/h	159.60	
Material Cost	73.59	
Total Paint Including Material		233.19
Repair Cost Excludes GST		14,867.39
GST (+9.00%)		1,338.07
Repair Cost Included GST		16,205.46

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.