



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhhb.com.sg
Company Reg. No. 202341776E

TP INC
Veron.

Vehicle No.: SNP5539E
Make/Model : Toyota Altis
Chassis no.: MR2BE3BE700028584
Year of Manufacture : 2024

Date of survey: 27 Nov 2024
Surveyor: Adrian
Company : LKK
Ins Company : Income Insurance
TP vehicle No.: SKZ7136D

Accident Date : 23 Nov 2024

Type of repair: Lump Sump

Estimate cost of repairs

| Qty | Part Description | Unit Price | Total Price |
|-----------------|--|-------------|----------------------------|
| 1 pc | Rear bumper <i>Distid</i> | \$ 824.00 | \$ 824.00 ✓ 125 |
| <i>LH</i> 2 pcs | Rear bumper retainer RH/LH <i>neu</i> | \$ 153.00 | \$ 306.00 + |
| 1 pc | Bootlid <i>Distid</i> | \$ 1,314.00 | \$ 1,314.00 - |
| <i>LH</i> 2 pcs | Bootlid hinge RH/LH <i>neu</i> | \$ 99.00 | \$ 198.00 + 99 |
| 2 pcs | Bootlid reflector RH/LH <i>neu</i> | \$ 160.00 | \$ 320.00 + |
| 2 pcs | Bootlid reflector chrome moulding RH/LH <i>neu</i> | \$ 58.00 | \$ 116.00 + |
| 1 pc | Emblem "Altis" | \$ 77.00 | \$ 77.00 ✓ |
| 1 pc | Emblem "Corolla" | \$ 77.00 | \$ 77.00 - |
| 1 pc | Emblem "Toyota" | \$ 88.00 | \$ 88.00 - |
| 1 pc | Rear end panel <i>Distid</i> | \$ 932.00 | \$ 932.00 - 795 |
| 1 pc | Rear end panel top garnish <i>Distid</i> | \$ 375.00 | \$ 375.00 - |
| 1 pc | Floor panel <i>neu</i> | \$ 1,436.00 | \$ 1,436.00 + |
| 1 pc | Rear keyless sensor <i>neu</i> | \$ 100.00 | \$ 100.00 + |
| 1 set | Reverse sensor <i>neu</i> | \$ 223.00 | \$ 223.00 ✓ |
| 1 pc | Rear bumper reinforcement <i>Distid</i> | \$ 512.00 | \$ 512.00 ✓ 410 |
| | | | \$ 6,898.00 |
| | | | \$ (1,379.60) |
| | | | \$ 5,518.40 |

Less 20% *25%*
4183.
was 25%: 3137.25

| | | | |
|-------|---|-------------|-----------|
| 1 set | Rear bumper clips <i>neu</i> | \$ 50.00 SN | 30 |
| 1 set | Bootlid trimboard clips <i>neu</i> | \$ 50.00 SN | + |
| 1 set | Rear end panel sealant <i>neu</i> | \$ 60.00 SN | ✓ |
| 1 set | Rear floor panel sealant <i>neu</i> | \$ 60.00 SN | + |
| 1 set | Rear number plate with casing <i>Best</i> | \$ 60.00 SN | ✓ |
| | | | \$ 280.00 |

150

Lock
weatherstrip
Floor panel top board



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921

Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhb.com.sg

Company Reg. No. 202341776E

| | | | |
|-------|--|----|--|
| 1 job | To putty and spray painting | \$ | 800.00 ¹²⁰⁰ 800 1000. |
| 1 job | Wiring Charges | \$ | 60.00 30. |
| 1 job | Tuff coat | \$ | 60.00 ✓ |
| 1 job | To remove, refix reverse camera | \$ | 80.00 50 ¹⁹⁹⁰ |
| 1 job | To remove, replace reverse sensor | \$ | 100.00 50 |
| 1 job | Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts. | \$ | 1,000.00 800 |

\$ 2,100.00

Grand-total

\$ 7,898.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Lj

P/P 28/11/24.

07 days

Supplementary: 1422.75

Total: 6700 ✓

CP/P



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhb.com.sg
Company Reg. No. 202341776E

Vehicle No.: SNP5539E
Make/Model : Toyota Altis
Chassis no.: MR2BE3BE700028584
Year of Manufacture : 2024

Date of survey: 27 Nov 2024
Surveyor: Adrian
Company : LKK
Ins Company : Income Insurance
TP vehicle No.: SKZ7136D

Accident Date : 23 Nov 2024

Type of repair: Lump Sump

Supplementary

| Qty | Part Description | Unit Price | Total Price |
|----------|--|-------------|--------------------------|
| 1 pc | Bootlid weatherstrip <i>at</i> | \$ 286.00 | \$ 286.00 ✓ |
| 2 pcs | Bootlid lock <i>part</i> | \$ 553.00 | \$ 1,106.00 ✓ <i>553</i> |
| 1 pc | Taillamp LH <i>crack</i> | \$ 1,887.00 | \$ 1,887.00 ✓ <i>945</i> |
| 1 pc | Rear LH tail lamp side cover <i>at</i> | \$ 48.00 | \$ 48.00 ✓ |
| 1 pc | Taillamp bracket <i>LH cracked</i> | \$ 153.00 | \$ 153.00 ✓ <i>65</i> |
| | | | <hr/> |
| | | | \$ 3,480.00 |
| Less 25% | | | \$ (870.00) |
| | | | <hr/> |
| | | | \$ 2,610.00 |

1897
was 25% : 1422.75