



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhhbm.com.sg
Company Reg. No. 202341776E

Vehicle No.: SNP5539E
Make/Model : Toyota Altis
Chassis no.: MR2BE3BE700028584
Year of Manufacture : 2024

Date of survey: 27 Nov 2024
Surveyor: Adrian
Company : LKK
Ins Company : Income Insurance
TP vehicle No.: SKZ7136D

Accident Date : 23 Nov 2024

Type of repair: Lump Sump

Supplementary

Qty	Part Description	Unit Price	Total Price
1 pc	Bootlid weatherstrip <i>at</i>	\$ 286.00	\$ 286.00 ✓
2 pcs	Bootlid lock <i>part</i>	\$ 553.00	\$ 1,106.00 ✓ <i>553</i>
1 pc	Taillamp LH <i>crack</i>	\$ 1,887.00	\$ 1,887.00 ✓ <i>945</i>
1 pc	Rear LH tail lamp side cover <i>at</i>	\$ 48.00	\$ 48.00 ✓
1 pc	Taillamp bracket <i>LH cracked</i>	\$ 153.00	\$ 153.00 ✓ <i>65</i>
			<hr/>
			\$ 3,480.00
Less 25%			\$ (870.00)
			<hr/>
			\$ 2,610.00

1897
was 25% : 1422.75