

(08/11/13) Wef

REF:

ASS. REC. BY: Marcus

CS/CT/24/10590/Unh3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBL 7941B

at Workshop m/s

J.1 Ave. 2.30pm

of

Insured:

Gx 6321P

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$75k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

1.3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3100k

Vehicle: IN / OUT

Date:

Person Contacted:

A 7A 825233

Veh No:

GBL 7941B

Yr Regn:

22/04/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA)

Make:

Toyota Hiace 2.0 DX c.c. 1998

Colour

S.h

A/C: Insured / Std / NI / NA

Sp. Reading

54837

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TRH 2000353029

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-1215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/11/24

D.O.I.

27/11/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 10k.

20/11/24 21:20 2209.05 informed Jones (Red. \$1801.60, 38%)

re-finalise \$3307.05 and 4 days

(red, \$1403.6, 29%)(parts markup 10%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	100K
Vehicle Details	
Vehicle No.:	GBL7941B
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 2.0 DX AUTO
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	1TR2417751
Chassis No.:	TRH2000353029
Maximum Power Output:	-
Open Market Value:	\$26,470.00
Original Registration Date:	22 Apr 2022
First Registration Date:	22 Apr 2022
Transfer Count:	0
Actual ARF Paid:	\$1,324.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Apr 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,088.00
COE Rebate Amount:	\$25,233.00
Total Rebate Amount:	\$25,233.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 27 Nov 2024

OK



Home Used Cars Listing

All Category



Filter

2

Search

Save Search



Any status X 2022 X

Sort by Any Status, Date Posted (Newest)

20 Vehicles

Car Make

Car Model

Price Range

Depreciation

2022

Mileage



PREMIUM AD

Toyota Hiace 2.0A DX **\$86,888**
 Instl. \$1,145 /mth

\$11,880 /yr 21-Mar-2022
 (7yrs 3mths COE left) 20,000 km 1,998 cc 31 Owner
 4ForWheel Pte Ltd|Posted 27-Nov-2024

☐ Compare

PREMIUM AD

Toyota Hiace 2.0A DX **\$81,800**
 Instl. \$1,078 /mth

\$10,650 /yr 01-Aug-2022
 (7yrs 8mths COE left) N.A. 1,998 cc 31 Owner

Superb nice carplate number worth \$3888 +, 1 owner, cheapest, high spec, original LED light with rear aircon unit, ready to cash and carry anytime, 100% loan also welcome, high trade in and high warranty and servicings package! Call us now, we settle your commercial needs.

1F Motoring Pte Ltd|Posted 26-Nov-2024

☐ Compare

PREMIUM AD

Toyota Hiace 2.0A DX **\$80,988**
 Instl. \$1,067 /mth

\$11,300 /yr 28-Jan-2022
 (7yrs 2mths COE left) N.A. 1,998 cc 31 Owner

1 owner. Low mileage. Enjoy 2 years unlimited mileage warranty on gearbox and engine and lifetime free servicing. Well maintained by previous owner, buy with peace of mind and save your future money! Offer high trade in! Full loan available and 100% loan guaranteed approve, fast handover. Call now for viewing and test drive.

ABS Bus Pte Ltd|Posted 26-Nov-2024

☐ Compare

Compare

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Insurer Reference: GBL7941B
Repairer Reference: GBL7941B
Date calculated: 26/11/2024 4:28 PM

Full Report
Registration: GBL7941B
Printed: 26/11/2024 4:29 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	GBL7941B	Date of Incident:	21/11/24
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	HIACE		
Sub Model:	BASE MODEL		
Model Sheet Number:	70 84 01		
Registration:	GBL7941B		
VIN number:	TRH2000353029		
Odometer:	54448		
Model Specs			
10-SEATS	WHEELBASE 3110MM	L/SLIDING DOOR	VAN
TWO COAT METALLIC	PREPARE OFF VEHICLE		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not authorized
27/11/24
Theoph. Sekapalan
p/p \$2909.05
4 days

3307.05

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Type Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Spare Tyre Brand	Tread (Spare), mm
------------------	-------------------

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	R + R REAR CENTRE CARPET RETAINER		2.0	8.40
NO NUMBER	RENEW REAR END PANEL		46.0	193.20
	INCLUDES: R + R BUMPER, TAILGATE SEAL, LOCK STRIKER PLATE AND SPARE WHEEL CARRIER			
B390	RENEW TAILGATE		30.0	126.00
	INCLUDES: R + R TAILGATE AND NECESSARY ATTACHED PARTS			
	DOES NOT INCLUDE: R + R REAR WINDOW			
G040	R + R TAILGATE REAR SCREEN		23.0	96.60
B407	R + R LEFT TAILLAMP		1.0	4.20
B407	R + R RIGHT TAILLAMP		1.0	4.20
NO NUMBER	R + R L/R BUMPER CORNER		3.0	12.60
NO NUMBER	R + R R/R BUMPER CORNER		3.0	12.60
511201 ZAX	R + R SPARE WHEEL CARRIER		3.0	12.60

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	11.20	112.0	470.40
Total of Labour			470.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR PANEL NEW PART PAINTING	15.0
	REAR BUMPER NEW PART PAINT K1G/P	17.0
	L/R BUMPER CORNER REPAIR PAINT PLASTIC	9.0
	R/R BUMPER CORNER REPAIR PAINT PLASTIC	9.0
	BOOTLID/TAILGATE REPAIR PAINTING >50%	42.0

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	14.30
2581	REAR BUMPER NEW PART PAINT K1G/P	63.00
2591	L/R BUMPER CORNER REPAIR PAINT PLASTIC	5.67
2592	R/R BUMPER CORNER REPAIR PAINT PLASTIC	5.67
2931	BOOTLID/TAILGATE REPAIR PAINTING >50%	70.31

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		92.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	125.0	525.00

Material Cost - Paint

	Price SGD
New Part Painting	14.30
New Part Painting - Plastic K1G/PUR	63.00
Repair Painting	70.31
Repair Painting Plastic	11.34
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	200.25

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
2411	REAR SCREEN BOND KIT	PZ49I 00C1131			
2581	REAR BUMPER	52159 26470	Original	NS	0.00 X
2591	L/R BUMPER CORNER	52166 26030A0	Original	D.S -	400.00 ✓
2592	R/R BUMPER CORNER	52165 26030A0	Original	11 X	80.00 X
2702	REAR NUMBER PLATE	KNPL6	Original	12 X	80.00 X
2711	REAR PANEL	57069 26180	Original	D.P.ME -	30.00 ✓
2931	BOOTLID/TAILGATE	67005 26A31	Original	R	350.00 X
2944	BOOT/TAILGATE SEAL	67881 26103	Original	DD -	850.00 ✓
				7M ✓	150.00 ✓

Code	Description	Part Number	Part Source	Price SGD
2973	REAR LOCK CATCH	69430 95300	Original	11 X 55.00 X
3015	BADGE TOYOTA	90975 02064	Original Kiv	11 X 50.00 X
3020	BADGE HIACE	75441 26281	Original Kiv	11 X 30.00 X
3281	L/R LAMP	81561 26200	Original	11 X 150.00 X
3282	R/R LAMP	81551 26201	Original	11 X 150.00 X
4986	REAR CARPET	67935 26190	Original	11 X 120.00 X
	MOULDING			
9690	SPARE WHEEL SUPPORT	51903 26661	Original	11 X 160.00 X

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	tailgate lock - Daye/JM @ 150 ✓	0.00
Subtotal		2,655.00
Total	tailgate lock cover, 2x @ 40 ✓ Rear bumper inner step panel @ 170 bent ✓	2,655.00

Extras

Code	Description	Price SGD
1000	REVERSE CAMERA REVERSE CAMERA	11 180.00*
1001	RR BUMPER REVERSE SENSOR	20 malfunction 250.00*
1002	WIRING WIRING	20 - 50.00*
1003	70KM/H STICKER	11 10.00*
1004	6 PAX STICKER	11 10.00*
	Total Extras	500.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	2,655.00	2,655.00
Labour Time Base 10 WU/h		
Total 112.0 WU X 42.00 SGD/h	470.40	
Total of Labour		470.40
Total Of Extras		500.00
Paint Work Time Base 10 WU/h		
Labour Cost 125.0 WU X 42.00 SGD/h	525.00	
Material Cost	200.25	
Total Paint Including Material		725.25
Repair Cost Excludes GST		4,350.65
GST (+9.00%)		391.56
Repair Cost Included GST		4,742.21

4710.65

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.