

(08/11/13) wef

REF:

ASS. REC. BY: Marcus

CS/CT/24/10590/Unh3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: GBL 79413
at Workshop m/s J. A. Ave. 2.30pm
of _____
Insured: Gx 6321P
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: GBL 79413 Yr Regn: 22/04/22
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover
Truck / Trailer or CA
Make: Toyota hino 2.0 DX c.c 1998
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 54837 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: TRH 2000353029
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: NA / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 195-1215

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$75k.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: 1.3.1 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS 3100k
Date: _____ Person Contacted: 27A 825233
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front 6 mm Rear 6 mm
R/Bal. _____ mm R/Bal. _____ mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 21/11/24 D.O.I. 27/11/24

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Day 10k.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	100K
Vehicle Details	
Vehicle No.:	GBL7941B
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 2.0 DX AUTO
Primary Colour:	Silver
Manufacturing Year:	2021
Engine No.:	1TR2417751
Chassis No.:	TRH2000353029
Maximum Power Output:	-
Open Market Value:	\$26,470.00
Original Registration Date:	22 Apr 2022
First Registration Date:	22 Apr 2022
Transfer Count:	0
Actual ARF Paid:	\$1,324.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Apr 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,088.00
COE Rebate Amount:	\$25,233.00
Total Rebate Amount:	\$25,233.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 27 Nov 2024

OK

Home Used Cars Listing

All Category

Filter

2

Search

Save Search

Any status X2022 X

Sort by Any Status, Date Posted (Newest)

20 Vehicles

Car Make

Car Model

Price Range

Depreciation

2022

Mileage

- 

Toyota Hiace 2.0A DX

\$86,888

\$11,880 /yr

21-Mar-2022

(7yrs 3mths COE left)

20,000 km1,998 cc31 Owner

Instl. \$1,145 /mth

4ForWheel Pte Ltd|Posted 27-Nov-2024

Compare
- 

Toyota Hiace 2.0A DX

\$81,800

\$10,650 /yr

01-Aug-2022

(7yrs 8mths COE left)

N.A.1,998 cc31 Owner

Instl. \$1,078 /mth

Superb nice carplate number worth \$3888 +, 1 owner, cheapest, high spec, original LED light with rear aircon unit, ready to cash and carry anytime, 100% loan also welcome, high trade in and high warranty and servicings package! Call us now, we settle your commercial needs.

IF Motoring Pte Ltd|Posted 26-Nov-2024

Compare
- 

Toyota Hiace 2.0A DX

\$80,988

\$11,300 /yr

28-Jan-2022

(7yrs 2mths COE left)

N.A.1,998 cc31 Owner

Instl. \$1,067 /mth

1 owner. Low mileage. Enjoy 2 years unlimited mileage warranty on gearbox and engine and lifetime free servicing. Well maintained by previous owner, buy with peace of mind and save your future money! Offer high trade in! Full loan available and 100% loan guaranteed approve, fast handover. Call now for viewing and test drive.

ABS Bus Pte Ltd|Posted 26-Nov-2024

Compare

Jin Auto Services Pte Ltd
#01-410/412, 14 Defu Lane 10
539195

Insurer Reference: GBL7941B
Repairer Reference: GBL7941B
Date calculated: 26/11/2024 4:28 PM

Full Report
Registration: GBL7941B
Printed: 26/11/2024 4:29 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	GBL7941B	Date of Incident:	21/11/24
Estimated Repair Time:	6	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	HIACE
Sub Model:	BASE MODEL
Model Sheet Number:	70 84 01
Registration:	GBL7941B
VIN number:	TRH2000353029
Odometer:	54448

Model Specs

10-SEATS	WHEELBASE 3110MM	L/SLIDING DOOR	VAN
TWO COAT METALLIC	PREPARE OFF VEHICLE		

not full on
was
27/11/24
theoph. bekepo
p/p s
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	----------------------------	---------------------------	---------------------------	----------------------------	----------------------------	-----------------------------	-----------

Spare Tyre Brand Tread (Spare), mm

Labour

Code	Description	Time Base 10 WU/h		Price = 42.00 SGD/h	
		WU	Price SGD	WU	Price SGD
NO NUMBER	R + R REAR CENTRE CARPET RETAINER	2.0	8.40		
NO NUMBER	RENEW REAR END PANEL INCLUDES: R + R BUMPER, TAILGATE SEAL, LOCK STRIKER PLATE AND SPARE WHEEL CARRIER	46.0	193.20		
B390	RENEW TAILGATE INCLUDES: R + R TAILGATE AND NECESSARY ATTACHED PARTS DOES NOT INCLUDE: R + R REAR WINDOW	30.0	126.00		
G040	R + R TAILGATE REAR SCREEN	23.0	96.60		
B407	R + R LEFT TAILLAMP	1.0	4.20		
B407	R + R RIGHT TAILLAMP	1.0	4.20		
NO NUMBER	R + R L/R BUMPER CORNER	3.0	12.60		
NO NUMBER	R + R R/R BUMPER CORNER	3.0	12.60		
511201 ZAX	R + R SPARE WHEEL CARRIER	3.0	12.60		

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	11.20	112.0	470.40
Total of Labour			470.40

Paint

Paint Work	SYSTEM AZT	Time Basis	10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	REAR PANEL NEW PART PAINTING	15.0	
	REAR BUMPER NEW PART PAINT K1G/P	17.0	
	L/R BUMPER CORNER REPAIR PAINT PLASTIC	9.0	
	R/R BUMPER CORNER REPAIR PAINT PLASTIC	9.0	
	BOOTLID/TAILGATE REPAIR PAINTING >50%	42.0	

Paint Material Per Part

Code	Description	Price SGD
2711	REAR PANEL NEW PART PAINTING	14.30
2581	REAR BUMPER NEW PART PAINT K1G/P	63.00
2591	L/R BUMPER CORNER REPAIR PAINT PLASTIC	5.67
2592	R/R BUMPER CORNER REPAIR PAINT PLASTIC	5.67
2931	BOOTLID/TAILGATE REPAIR PAINTING >50%	70.31

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		92.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	12.50	125.0

Material Cost - Paint	Price SGD
New Part Painting	14.30
New Part Painting - Plastic K1G/PUR	63.00
Repair Painting	70.31
Repair Painting Plastic	11.34
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	200.25

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
2411	REAR SCREEN BOND KIT PZ49I 00C1131				0.00
2581	REAR BUMPER	52159 26470	Original	Dis —	400.00
2591	L/R BUMPER CORNER	52166 26030A0	Original	11X	80.00
2592	R/R BUMPER CORNER	52165 26030A0	Original	12X	80.00
2702	REAR NUMBER PLATE	KNPL6	Original	?	30.00
2711	REAR PANEL	57069 26180	Original	?	350.00
2931	BOOTLID/TAILGATE	67005 26A31	Original	00 —	850.00
2944	BOOT/TAILGATE SEAL	67881 26103	Original	?	150.00

Code	Description	Part Number	Part Source	Price SGD
2973	REAR LOCK CATCH	69430 95J00	Original	her / 55.00
3015	BADGE TOYOTA	90975 02064	Original	her / 50.00
3020	BADGE HIACE	75441 26281	Original	her / 30.00
3281	L/R LAMP	81561 26200	Original	? 150.00
3282	R/R LAMP	81551 26201	Original	? 150.00
4986	REAR CARPET MOULDING	67935 26190	Original	? 120.00
9690	SPARE WHEEL SUPPORT	51903 26661	Original	11X 160.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,655.00
u: Used parts	Total			2,655.00

Extras

Code	Description	Price SGD
1000	REVERSE CAMERA REVERSE CAMERA	? 180.00*
1001	RR BUMPER REVERSE SENSOR	200 m, h, f, u 250.00*
1002	WIRING WIRING	20 50.00*
1003	70KM/H STICKER	her / 10.00*
1004	6 PAX STICKER	her / 10.00*
	Total Extras	500.00

Final Calculation

	SGD	SGD
Parts	2,655.00	
Total Parts		2,655.00
Labour Time Base 10 WU/h		
Total 112.0 WU X 42.00 SGD/h	470.40	
Total of Labour		470.40
Total Of Extras		500.00
Paint Work Time Base 10 WU/h		
Labour Cost 125.0 WU X 42.00 SGD/h	525.00	
Material Cost	200.25	
Total Paint Including Material		725.25
Repair Cost Excludes GST		4,350.65
GST (+9.00%)		391.56
Repair Cost Included GST		4,742.21

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS