

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **Liberty Insurance Pte Ltd**
One Raffles Quay, #25-01, North Tower,
Singapore 048583

Attn : Motor Claims Department
Tel : 62218611
Fax : 62241047

Estimate bill : TT 43 / 24 / TP / WT

Registration No : SLG238C

Make / model : MB E200 (213)

Date : 25 / 11 / 2024

Mileage :

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SNG3226M AND SLG238C ALONG
BUYONG ROAD ON 15 NOVEMBER 2024 AT ABOUT 0855HRS.

1pc	Front RH fender	1162	\$	1,552.00	✓
1pc	Front RH door	131/wrp	\$	2,771.00	✓
1pc	Front RH door pillar outer garnish		\$	194.00	✓
1pc	Front RH door weather strip		\$	444.00	✓
1pc	RH door side skirt chrome trimming		\$	278.00	✓
	Sub total :		\$	5,239.00	
	Less 10% discount :	10%	\$	523.90	
	A total :		\$	4,715.10	

Remove & refit front bumper.

Remove and refit front RH fender.

Remove & transfer front RH door necessary attachment spare parts item.

Remove and refit front RH door, front RH door pillar outer garnish, front RH door weather strip, RH door side skirt chrome trimming.

Putty / primer application, spray painting front RH fender, front RH door.

Grand final amount :

\$	900.00	450
\$	500.00	✓
\$	6,115.10	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: