

Tropical Tech Automobile Services

BLK 5030 ANG MO KIO AVENUE 3 #01-201 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : Liberty Insurance Pte Ltd
One Raffles Quay, #25-01, North Tower,
Singapore 048583

Not Notion
Putty B4 pain
4 days

Estimate bill : TT 43 / 24 / TP / WT

Registration No : SLG238C

Make / model : MB E200 (213)

Attn : Motor Claims Department
Tel : 62218611
Fax : 62241047

Date : 25 / 11 / 2024

Mileage :
**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SNG3226M AND SLG238C ALONG
BUYONG ROAD ON 15 NOVEMBER 2024 AT ABOUT 0855HRS.**

1pc Front RH fender
1pc Front RH door
1pc Front RH door pillar outer garnish
1pc Front RH door weather strip
1pc RH door side skirt chrome trimming
Sub total :
Less 10% discount :
A total :

\$	1,552.00
\$	2,771.00
\$	194.00
\$	502.00
\$	278.00
\$	5,239.00
\$	523.90
\$	4,715.10

Remove & refit front bumper.

Remove and refit front RH fender.

Remove & transfer front RH door necessary attachment spare parts item.

Remove and refit front RH door, front RH door pillar outer garnish, front RH door weather strip, RH door side skirt chrome trimming.

Putty / primer application, spray painting front RH fender, front RH door.

Grand final amount :

\$	400
\$	900.00
\$	440
\$	500.00
\$	6,115.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

(Authorised Signature)

William Tan

