

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

TP INSURER:

VIENNA DIONNE CHIA CHYE JUAN

Singapore

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	25/11/2024
Vehicle Reg. No.:	SJX7963E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	VIENNA DIONNE CHIA CHYE JUAN		
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	13/07/2010
Vehicle Colour:	RED	Chassis No:	KMH DU41BMAU020201
Engine No:	G4FCAU848739		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 ✓		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

Not Notified
61 Pmp @ 5900h
Paying After Repair

COST OF CLAIMS

	Amount
Parts	8,505.60
Miscellaneous Items	380.00
Labour	3,870.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,755.60
+ GST 9.00% (S\$)	1,148.00
Nett Amount (S\$)	13,903.60

This claim is handled by: GOH JACQUELINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Nov 2024)
Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJX7963E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT RH DOOR	0.00	0.00	R *1,090.00 F X
2	1		*FRONT RH DOOR OUTER MOUNDLING	0.00	0.00	Rn *45.00 F X
3	1		*FRONT RH DOOR RUBBER @ DOOR	0.00	0.00	Rn *106.00 F X
4	1		*FRONT RH DOOR RUBBER @ BODY	0.00	0.00	SL *97.00 F
5	1		*FRONT RH FENDER	0.00	0.00	Rn *440.00 F
6	1		*FRONT RH FENDER INNER SHIELD	0.00	0.00	CM *57.00 F
7	1		*FRONT BUMPER	0.00	0.00	CM *435.00 F
8	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	CM *22.00 F
9	1		*FRONT HEADLAMP RH	0.00	0.00	mi *480.00 F
10	1		*FRONT HEADLAMP LOWER BRACKET	0.00	0.00	CM *790.00 F
11	1		*FRONT SHOCK ABSORBER RH	0.00	0.00	Rn *234.00 F 2
12	1		*FRONT KUNCKLE RH	0.00	0.00	Rn *309.00 F
13	1		*FRONT LOWER ARM RH	0.00	0.00	Di *282.00 F 2
14	1		*FRONT STABILIZER LINKAGE RH	0.00	0.00	Sn *200.00 F X
15	1		*FRONT TIE ROD RH	0.00	0.00	Sn *95.00 F X
16	1		*FRONT RACK END RH	0.00	0.00	Rn *55.00 F
17	1		*FRONT WHEEL BEARING RH	0.00	0.00	Rn *124.00 F
18	1		*FRONT BONNET	0.00	0.00	Rn *1,067.00 F
19	2		*FRONT BONNET HINGE	0.00	0.00	Rn *260.00 F X
20	1		*RIM	0.00	0.00	Del *900.00 F 350.
Sub Total (S\$)						7,088.00
+ Margin on L,N Items 20.00% (S\$)						1,417.60
Total Parts (S\$)						8,505.60

F=Franchise part.

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BUMPER CLIPS
2	1	FRONT FENDER INNER SHIELD CLIPS
3	1	TYRE

Sub Total (S\$)

380.00

Me 50.00
 20 50.00
 70 280.00
 1965 702
 380.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	SPRAY PAINT ON ALL AFFECTED AREA
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA
3	TO CHECK WIRING SYSTEM
4	TO APPLY ANTI RUST TREATMENT
5	WHEEL ALIGNMENT
6	TO REMOVE/REFIX/REPLACE UNDERCARRIAGE
7	TO REMOVE/REPLACE/REFIX FRONT RH DOOR WINDOW GLASS, MECHANISM & ETC TO NEW DOOR

New	800	1,500.00
New	650	1,500.00
New	200	100.00
New	600	120.00
New	600	150.00
New	200	350.00
New	200	150.00

Gross Labour Cost (S\$)

3,870.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: