

ASS. REC. BY:

REF:

CS/ 105 24110593/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$8,500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STX 7963E

Yr Regn:

07, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avento c.c

1591

Colour

M. Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

182218

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH041BMAU020201

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

6 mm

R/Bal.

5 mm

L/Bal.

6 mm

L/Bal.

5 mm

D.O.A.

25/11/24

D.O.I.

28/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Fr & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / 67A rhae @ 2032.00

12/12

61 Rpt @ 5900/r Colur Cted \$6855.60, 5471)

Date/Time, File Pass to?

☐

Prell. Report

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

MER-TP

Lump Sum / I.B.I. (\$)

5900

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S - RS. SI

Fees

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto. Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

TP INSURER:

ECICS Limited (HQ)

VIENNA DIONNE CHIA CHYE JUAN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	25/11/2024
Vehicle Reg. No.:	SJX7963E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	VIENNA DIONNE CHIA CHYE JUAN		
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date:	13/07/2010
Vehicle Colour:	RED		
Engine No:	G4FCAU848739	Chassis No:	KMH DU41BMAU020201
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 ✓		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

NOT Notified
L1 Rep @ 5900h
Pickup After Repair

COST OF CLAIMS	Amount
Parts	8,505.60
Miscellaneous Items	380.00
Labour	3,870.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	12,755.60
+ GST 9.00% (S\$)	1,148.00
Nett Amount (S\$)	13,903.60

This claim is handled by: GOH JACQUELINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 27 Nov 2024)

Parts: 143

HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJX7963E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT RH DOOR	0.00	0.00	R *1,090.00 F X
2	1		*FRONT RH DOOR OUTER MOUNDLING	0.00	0.00	R *45.00 F X
3	1		*FRONT RH DOOR RUBBER @ DOOR	0.00	0.00	P2 *106.00 F X
4	1		*FRONT RH DOOR RUBBER @ BODY	0.00	0.00	Sh *97.00 F
5	1		*FRONT RH FENDER	0.00	0.00	B *440.00 F
6	1		*FRONT RH FENDER INNER SHIELD	0.00	0.00	CM *57.00 F
7	1		*FRONT BUMPER	0.00	0.00	CM *435.00 F
8	1		*FRONT BUMPER SIDE RETAINER RH	0.00	0.00	CM *22.00 F
9	1		*FRONT HEADLAMP RH	0.00	0.00	mi *480.00 F
10	1		*FRONT HEADLAMP LOWER BRACKET	0.00	0.00	CM *790.00 F
11	1		*FRONT SHOCK ABSORBER RH	0.00	0.00	B *234.00 F
12	1		*FRONT KUNCKLE RH	0.00	0.00	B *309.00 F
13	1		*FRONT LOWER ARM RH	0.00	0.00	di *282.00 F
14	1		*FRONT STABILIZER LINKAGE RH	0.00	0.00	sa *200.00 F
15	1		*FRONT TIE ROD RH	0.00	0.00	sa *95.00 F
16	1		*FRONT RACK END RH	0.00	0.00	sa *55.00 F
17	1		*FRONT WHEEL BEARING RH	0.00	0.00	sa *124.00 F
18	1		*FRONT BONNET	0.00	0.00	B *1,067.00 F
19	2		*FRONT BONNET HINGE	0.00	0.00	R *260.00 F
20	1		*RIM	0.00	0.00	PC *900.00 F
Sub Total (S\$)						7,088.00
+ Margin on L,N Items 20.00% (S\$)						1,417.60
Total Parts (S\$)						8,505.60

F=Franchise part.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BUMPER CLIPS
2	1	FRONT FENDER INNER SHIELD CLIPS
3	1	TYRE

Sub Total (S\$)

50.00
50.00
280.00
380.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,500.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,500.00
3	TO CHECK WIRING SYSTEM	New	100.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00
5	WHEEL ALIGNMENT	New	150.00
6	TO REMOVE/REFIX/REPLACE UNDERCARRIAGE	New	350.00
7	TO REMOVE/REPLACE/REFIX FRONT RH DOOR WINDOW GLASS, MECHANISM & ETC TO NEW DOOR	New	150.00

Gross Labour Cost (S\$)

3,870.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: