



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 26-11-2024
 VEHICLE : SND 8536 G
 MAKE/MODEL : TOYOTA / ALPHARD
 CHASSIS NO : JTNHS3DH508063655
 MILEAGE :
 TYRE SIZE :
 DOA : 22-11-2024
 TP INSURANCE : INCOME

NOT withold
Repair After Rain
2day
11 Day @ 1350/

List items

01 PC FRONT FENDER UPPER GLASS (RH)
 01 PC SIDE MIRROR ASSY (RH) *1520.80*
 01 PC SIDE MIRROR COVER (RH)

Wt \$ 245.14 ✓
Paint \$ 1,778.45 ✓
Sur R \$ ~~148.82~~ X
\$ 2,172.41

25%

Special Nett Item:

01 PC GLASS SEALANT

\$ *Net* 50.00 *35%*
\$ 50.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR
4. TO SUPPLY LABOUR TO REFIT GLASS
5. TO SUPPLY DIAGNOTIC & REPROGRAMMING

\$ 100.00 *80*
 \$ 100.00 *60*
 \$ 100.00
 \$ 200.00 *60*
 \$ 450.00 *120*
\$ 950.00

TOTAL PARTS \$ 2,172.41
SPECIAL NETT ITEM \$ 50.00
TOTAL LABOUR \$ 950.00
TOTAL COST OF REPAIR \$ 3,172.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: