

ASS. REC. BY:

REF: INC /

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$206k

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SD 85366Yr Regn: 01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy AlphardC.G. 2494Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 215351

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTNHS3DH508083655Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / Rlm or

Tyre Size: Goddard 225/60R17R: Kapsen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 22/11/24D.O.I. 28/11/2024

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rt RH door mirror & glass

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report  
☐ : Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

p Sum / I.B.I: (\$

TOTAL



# MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 26-11-2024  
VEHICLE : SND 8536 G  
MAKE/MODEL : TOYOTA / ALPHARD  
CHASSIS NO : JTNHS3DH508063655  
MILEAGE :  
TYRE SIZE :  
DOA : 22-11-2024  
TP INSURANCE : INCOME

NOT Withheld  
Recovery After Paim  
2 days

## List items

01 PC FRONT FENDER UPPER GLASS (RH)  
01 PC SIDE MIRROR ASSY (RH)  
01 PC SIDE MIRROR COVER (RH)

Wt \$ 245.14 ✓  
Pd / um \$ 1,778.45 ✓  
Per n \$ 148.82 X  
\$ 2,172.41

## Special Nett Item:

01 PC GLASS SEALANT

\$ 50.00 35in  
\$ 50.00

## Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR
4. TO SUPPLY LABOUR TO REFIT GLASS
5. TO SUPPLY DIAGNOTIC & REPROGRAMMING

\$ 100.00 84  
\$ 100.00 60l  
\$ 100.00  
\$ 200.00 60l  
\$ 450.00 7  
\$ 950.00

**TOTAL PARTS**

\$ 2,172.41

**SPECIAL NETT ITEM**

\$ 50.00

**TOTAL LABOUR**

\$ 950.00

**TOTAL COST OF REPAIR**

\$ 3,172.41

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: