

ASS. REC. BY:

REF:

05/11/24 110596/Kg/h3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$206K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PND 85366 Yr Regn: 01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____ (A) Wagon

Make: Toy Alphard C.C. 2494

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 215351 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTNHS3DH508083655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: Goodyear 225/60R17

R: Kapsen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 6 mm

L/Bal. 8 mm L/Bal. 6 mm

D.O.A. 22/11/24 D.O.I. 28/11/2024

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rt Rldoor mirror & 9/11

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/11 21Ry @ 1350h Carw Ured @ 1800.41, 57%

Date/Time, File Pass to?

03/12 110596

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Report Format: TP

Lump Sum / I.B.T. (\$)

1350



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 26-11-2024
VEHICLE : SND 8536 G
MAKE/MODEL : TOYOTA / ALPHARD
CHASSIS NO : JTNHS3DH508063655
MILEAGE :
TYRE SIZE :
DOA : 22-11-2024
TP INSURANCE : INCOME

NOT Authorized
Repairing After Paint
2 days
11/12/24 @ 1350/-

List items

01 PC FRONT FENDER UPPER GLASS (RH)
01 PC SIDE MIRROR ASSY (RH) 1520.80
01 PC SIDE MIRROR COVER (RH)

For \$ 245.14 ✓
Paint \$ 1,778.45 ✓
SRR \$ 148.82 X
\$ 2,172.41

259

Special Nett Item:

01 PC GLASS SEALANT

\$ 50.00 35m
\$ 50.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR
4. TO SUPPLY LABOUR TO REFIT GLASS
5. TO SUPPLY DIAGNOSTIC & REPROGRAMMING

\$ 100.00 80
\$ 100.00 60
\$ 100.00
\$ 200.00 60
\$ 450.00 120
\$ 950.00

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$ 2,172.41
\$ 50.00
\$ 950.00
\$ 3,172.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: