



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424

Main Line: 6265 0980 Fax: 6265 6068

Email: enquiry@asmauto.com.sg

Co. / GST Reg. No.: 201203813C



FROM : Jaclyn Lai
TEL. NO. : 6265 0026 / 9236 8218
EMAIL : jaclynlai@asmauto.com.sg

TO : Lonpac Insurance Bhd
ATTN : Motor Claim Department
TEL. NO. : 6250-7388
EMAIL : mt_claim@lonpac.com

CC : Ace Marine Supplies Pte. Ltd.

DATE : 27.11.2024

VEHICLE NO. : GBD 5503 M
MAKE & MODEL : TOYOTA DYNA 150 MANUAL
CHASSIS NO. : JTFAT35Y70K203796
ENGINE NO. : 1KD2455719 (2982cc)
LTA REG DATE : 04.12.2014 - 03.12.2024

CLAIM TYPE : Third Party - YQ 2092 K
D.O.A : 11.11.2024
CLAIM REF NO. : asm/AC24138/JL

QUOTATION FOR ACCIDENT REPAIR

<u>S/N</u>	<u>SPARE PARTS</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
1	Tailamp assy, LH	1	pc	\$ 160.00	\$ 160.00
2	Tailamp assy, RH	1	pc	\$ 160.00	\$ 160.00
SUB-TOTAL :					\$ 320.00
LESS 25% :					\$ 80.00
TOTAL :					\$ 240.00

<u>S/N</u>	<u>SPARE PARTS (SPECIAL NETT ITEMS)</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>AMOUNT</u>
1	Rear metal dropside w/aluminium chequer plate	1	pc	\$ 650.00	\$ 650.00
2	L-locking device for dropside, LH & RH	2	pcs	\$ 45.00	\$ 90.00
3	Sticker 70km/h	1	pc	\$ 10.00	\$ 10.00
4	Sticker 6pax	1	pc	\$ 12.00	\$ 12.00
5	Sticker "Toyota"	1	pc	\$ 80.00	\$ 80.00
6	Sticker "Dyna"	1	pc	\$ 40.00	\$ 40.00
7	Reverse buzzer	1	set	\$ 120.00	\$ 120.00
8	Rear emboss number plate	1	pc	\$ 40.00	\$ 40.00
S/N ITEMS TOTAL :					\$ 1,042.00

TOTAL PARTS : \$ 1,282.00

<u>S/N</u>	<u>LABOUR CHARGES</u>	<u>AMOUNT</u>
1	To jack, knock and straighten metal deck rear lower frame. Remove and replace damaged parts as above, check and reconnect tailamp & reverse buzzer wiring etc.	\$ 1,250.00
2	Spray painting	\$ 400.00
TOTAL LABOUR :		\$ 1,650.00

GRAND TOTAL : \$ 2,932.00