



ASM Automotive Services Pte Ltd

No 13, Pioneer Sector 1, Singapore 628424
Main Line: 6265 0980 Fax: 6265 6068
Email: enquiry@asmauto.com.sg
Co. / GST Reg. No.: 201203813C

bizSAFE₃

FROM : Jaclyn Lai
TEL. NO. : 6265 0026 / 9236 8218
EMAIL : jaclynlai@asmauto.com.sg

TO : Lonpac Insurance Bhd
ATTN : Motor Claim Department
TEL. NO. : 6250-7388
EMAIL : mt_claim@lonpac.com

CC : Ace Marine Supplies Pte. Ltd.

DATE : 27.11.2024

VEHICLE NO. : GBD 5503 M
MAKE & MODEL : TOYOTA DYNA 150 MANUAL
CHASSIS NO. : JTFAT35Y70K203796
ENGINE NO. : 1KD2455719 (2982cc)
LTA REG DATE : 04.12.2014 - 03.12.2029

CLAIM TYPE : Third Party - YQ 2092 K
D.O.A : 11.11.2024
CLAIM REF NO. : asm/AC24138/JL

QUOTATION FOR ACCIDENT REPAIR

S/N	SPARE PARTS	QTY	UOM	UNIT PRICE	AMOUNT
1	Tailamp assy, LH	1	pc	\$ 160.00	\$ cur 160.00
2	Tailamp assy, RH	1	pc	\$ 160.00	\$ an 160.00
SUB-TOTAL :					\$ 320.00
LESS 25% :					\$ 80.00
TOTAL :					\$ 240.00

S/N	SPARE PARTS (SPECIAL NETT ITEMS)	QTY	UOM	UNIT PRICE	AMOUNT
1	Rear metal dropside w/aluminium chequer plate	1	pc	\$ 650.00	\$ bt 650.00
2	L-locking device for dropside, LH & RH	2	pcs	\$ 45.00	\$ bt 90.00
3	Sticker 70km/h	1	pc	\$ 10.00	\$ net 10.00
4	Sticker 6pax	1	pc	\$ 12.00	\$ net 12.00
5	Sticker "Toyota"	1	pc	\$ 80.00	\$ net 80.00
6	Sticker "Dyna"	1	pc	\$ 40.00	\$ net 40.00
7	Reverse buzzer	1	set	\$ 120.00	\$ net 120.00
8	Rear emboss number plate	1	pc	\$ 40.00	\$ bt 40.00 30
S/N ITEMS TOTAL :					\$ 1,042.00
TOTAL PARTS :					\$ 1,282.00

S/N	LABOUR CHARGES	AMOUNT
1	To jack, knock and straighten metal deck rear lower frame. Remove and replace damaged parts as above, check and reconnect tailamp & reverse buzzer wiring etc.	\$ 1,250.00
2	Spray painting	\$ 300 400.00
TOTAL LABOUR		\$ 1,650.00
GRAND TOTAL		\$ 2,932.00

LKK Auto Consultancy notice
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Page 1 of 1