

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	04-12-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
<i>Hui Roy</i>	
VEHICLE DETAILS	
VEHICLE NO:	GBK2444H
MAKE & MODEL:	TOYOTA HIACE
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	14 November, 2024
TIME:	1450HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Painted</i>	1	\$ 2,155.30	\$ 2,155.30
2	TAILGATE LOCK <i>Re d</i>	1	\$ 350.00	\$ 350.00
3	TAILGATE WEATHERSTRIP <i>new</i>	1	\$ 390.00	\$ 390.00
4	REAR BUMPER <i>Re d</i>	1	\$ 580.00	\$ 580.00
5	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 85.00	\$ 85.00
6	STEP PANEL <i>Dented</i>	1	\$ 450.00	\$ 450.00
7	TAILLAMP <i>new</i>	1	\$ 380.00	\$ 380.00
8	TAILLAMP LOWER PANEL <i>new</i>	1	\$ 230.00	\$ 230.00
9	END PANEL <i>Dented</i>	1	\$ 630.00	\$ 630.00
10	END PANEL TOP GARNISH <i>new</i>	1	\$ 250.00	\$ 250.00

TOTAL PRICE \$ 5,500.30

LESS 25% \$ 1,375.08

SUB TOTAL PRICE \$ 4,125.23

4010.30
3007.72**SPECIAL NETT ITEMS**

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00
3	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	REVERSE SENSOR <i>Re d</i>	1	\$ 220.00	\$ 220.00

5	COMPANY DETAILS STICKER <i>new</i>	1	\$ 250.00	\$ 250.00	180
6	70KM/H <i>new</i>	1	\$ 50.00	\$ 50.00	15
7	6PAX <i>new</i>	1	\$ 50.00	\$ 50.00	15
			\$ 740.00		490

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,400.00	\$ 1,400.00	700
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,400.00	\$ 1,400.00	600
3	TUFF COAT	1	\$ 200.00	\$ 200.00	60
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	30
5	REMOVE AND REFIX REAR WINDSCREEN	1	\$ 120.00	\$ 120.00	✓
6	REMOVE AND REFIX TAILGATE MECHANISM	1	\$ 120.00	\$ 120.00	60
7	REMOVE AND REFIX REVERSE SENSOR AND SETTING	1	\$ 120.00	\$ 120.00	50

TOTAL \$ 3,440.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	4,865.23
TOTAL LABOUR COST	\$	3,440.00
TOTAL REPAIR COST	\$	8,305.23

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adm L/S 05/12/24

No of days: 06 days.

Total: 5117.72

L/S: 4.1K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: