

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Steve (LKK)

28/11/24, 11. Mon

w n

Vehicle number: SNA688U

Make & Model: AUDI A5 Sportback

Chassis number: WAUZZZF53MA016761

L/S

Lg AL sy, 6 dys

No.	Description of spare parts	Qty	Amount S\$
1	Rear bumper / RR	1	\$ 3,012.00
2	Rear bumper clips / RR	1set	\$ 30 / 80.00
3	Rear bumper LH side retainer / RR	1	\$ 45.00
4	Rear bumper lower spoiler X nn	1	\$ 837.00
5	Rear bumper LH side reverse sensor X nn	1	\$ 267.00
6	Rear bumper LH side corner reverse sensor X nn	1	\$ 267.00
7	Rear bumper reverse sensor rubber seal / RR	6	\$ 24.00
8	Rear bumper reverse sensor holders X nn	6	\$ 154.00
9	LH taillamp assy / RR / CUT	1	\$ 1,381.00
10	LH taillamp panel X nn	1	\$ 156.00
11	LH taillamp lock clips X nn	1set	\$ 60.00
12	Rear LH fender / RR	1	\$ 5,049.00
13	Rear LH fender inner trim X nn	1	\$ 938.00
14	Rear LH fender glass with rubber moulding X nn	1	\$ 773.00
15	Rear LH fender splash shield X nn	1	\$ 289.00
16	Rear LH fender splash shield clips X nn	1set	\$ 60.00
17	Rear LH fender inner lower duct X nn	1	\$ 78.00
18	Rear LH wheel bearing X nn	1	\$ 708.00
19	Rear LH knuckle arm X nn	1	\$ 2,301.00
20	Rear LH lower arm X nn	1	\$ 632.00
21	Rear LH shock absorber X nn	1	\$ 528.00
22	Rear LH upper arm X nn	1	\$ 440.00
23	Rear LH control arm X nn	1	\$ 437.00

2945 /

/

/

/

/

/

/

9474

-10%

8526.60

\$ 18,516.00

Part less-5% \$ 10% 925.80

Total: \$ 17,590.20

No.	Special Nett Items	Qty	Amount S\$
-----	--------------------	-----	------------

1	Rear LH fender glass sealant ✓ <i>nk</i>	1	\$ <i>30</i>	75.00
2	Rear LH fender glass inner seal X <i>nn</i>	1	\$	40.00
3	Rear LH fender joint sealant ✓ <i>nn</i>	1	\$	80.00
4	Rear LH sport rim ✓ <i>nn</i>	1	\$	1,800.00
5	Rear LH tyre ✓ <i>nn</i>	1	\$	700.00

Total: \$ 2,695.00 30

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ <i>800</i> 1,600.00
2	Spray painting on affected areas and panels	\$ <i>450</i> 1,500.00
3	Check wiring and lighting system on affected areas	\$ <i>50</i> 80.00
4	Apply rust coating chemical on affected areas and panels	\$ <i>30</i> 100.00
5	Remove and replace rear bumper reverse sensors (6 sensors)	\$ <i>30</i> 180.00
6	Remove and refit rear inner garnish and boards to assist repair	\$ <i>120</i> 400.00
7	Remove and replace rear LH fender glass to assist repair	\$ <i>80</i> 180.00
8	Test drive and adjust wheel alignment system	\$ X 180.00
9	Remove and replace rear undercarriage parts	\$ X 600.00

Total: \$ 3,220.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

1560

Spare Parts: \$ 17,590.20
Special Nett: \$ 2,695.00

10,116.60

L/S - 8093.28
= 8100

Labour: \$ 3,220.00

Total: \$ 23,505.20

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____