

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

TP 1st Cap.

VERON

FBK4479U

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBK4479U

Handle Bar	new	95	+
Balance	new	60	✓
Mirror	new	80	✓
Wind Screen	new	140	✓
Wind Screen Holder	at	60	✓
Brake Lever	lit	45	✓
Signal Light RH	new	85	+
Signal Light LH	new	85	✓
Meter	new	480	+
Head Light	lit	380	✓
Head Light Garnish	lit	65	✓
Lamp Stay	new	140	+
Fork Set	new	480	+
Fork Lower Clamp	new	380	✓
Steering Cone	new	140	✓
Rim	lit	320	✓
Disc	lit	120	✓
Brake Paddle	lit	85	✓
Front Footrest RH	lit	85	✓
Exhaust Pipe	new	850	+
Exhaust Pipe Cover	lit	65	✓
Lower Panner RH	new	65	✓
Side Fairing Rear RH	new	85	✓
End Fairing	new	65	✓
Side Fairing Rear LH	new	85	✓
Box	new	280	✓
Box Carrier	new	180	✓
Carrier Rubber	new	60	+
Front Footrest LH	new	85	+
Side Fairing LH	new	125	✓
Side Fairing Garnish LH	new	85	✓
Gear Paddle	new	85	+
Side Stand	new	95	+
Rear Mudguard	new	110	✓
Front Mudguard	new	120	✓
Tank	new	650	✓
IU Unit	new	250	+
Body Frame Repair		480	+
Body Frame Respray		180	150

4440

Less 10%: 3996.

→ see Behind

Number Plate Set

Labour

Towing

Total

~~60~~ 30

~~680~~ 380

50 ✓

8115

labour: 560

Adrian C
1/8 28/06/24.
05 days.

total: 4556
C/S: 3.6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: