



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110602/Evp3m4
16 RAFFLES QUAY	Date:	02/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 469X	Veh. Inspected	GBJ 1708J
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24010215MFCT	Excess	\$0.00
Assign From	SWEE KEONG	Assign Date	28/11/2024

### 2. Vehicle Details

Make & Model	TOYOTA DYNA 150	C.C	2982
Engine No.	1KD2834690	Year of Reg.	28/01/2019
Chassis No.	JTFAT35Y20K212082	Colour	WHITE
Odometer	201339 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15C	WEST LAKE	5
L/H Front Tyre	195R15C	WEST LAKE	5
R/H Rear Tyre	195R12LT	WEST LAKE	5
L/H Rear Tyre	195R12LT	WEST LAKE	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	19/11/2024	Inspection Date	28/11/2024
Survey held at	SE AUTOHUB PTE LTD - 56 LOYANG WAY 04-04 LOYANG ENTERPRISE BUILDING S'PORE 508775		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days