

TP

STRIDES
AUTOMOTIVE

84

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

A16

Section A - Accident Details

Registration Number	SHB5745X
Case Reference Number	TAX/11/24/2093
Registration Date	30/11/17
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEWIS JAMES DE SOUZA
Type of Accident	Side Swipe
Accident Date and Time	27/11/24 9:35 AM
Accident Reported Date and Time	28/11/24 12:25 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24110108
Special Instruction to ARC, if any	DAMAGE TO THE RIGHT SIDE MIRROR/AIG - LKK
Prepared Date and Time	28/11/24 1:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$0.00
Total Spray Cost	\$220.00	\$0.00
Total Spare Part Cost	\$1,255.35	\$0.00
Total Other Cost	\$280.00	\$0.00
TOTAL COST	\$2,093.35	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Mun San #	
ARC / Surveyor Sign Off Date		
Signature	gw	x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Steve (LKK)
28/11/24, 3:30pm
~ R
1 day
LPS
Hy AL Hy

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR RH PORTION	\$338.00	50
Total Labour	\$338.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY VIEW MIRROR	\$220.00	80
Total Spray Painting & Panel Beating	\$220.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO WASH AND VACUUM	\$60.00	X
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	30 ARC
TO REPLACE SUNDRY PARTS	\$100.00	X
Total Other Costs	\$280.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		8791047450	MIRROR ASSY, OUTER REAR VIEW, RH	1.00	\$1,556.00	25.00	\$1,167.00	Replace	✓ BR
		8791547070A1	COVER, OUTER MIRROR, RH	1.00	\$117.80	25.00	\$88.35	Replace	✓ M/S
Total					\$1,673.80		\$1,255.35		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor CI
Total									