

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0471/24

DATE : 25-NOV-2024

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

S(068877)

TEL : 65073848

FAX :

ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR LEE CHEE WEE

ADDRESS : BLK 145 POTONG PASIR AVENUE 2

#12-60

S(350145)

TELEPHONE NO : 68584498/97682138

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : V5022181

VEHICLE NO : SJV8095P

MODEL CODE : BDUARCAG11EHA-----

MODEL/YEAR : SYLPHY 1.5 4A/T SEDAN (II)

ENGINE NO : HR15294026B

CHASSIS NO : JN1BAAG11Z0110704

MILEAGE : 215674 KM

DATE IN : 25/11/2024

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 22/11/2024

- 9045 0084 elmer@fanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJV8095P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR BOTH RR FENDER & RR END PANEL,RENEW REAR BUMPER AND TRUNKLID	2580.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	2100.00	
3	ZZ/003	RENEW BOTH RR COMB LAMP AND TRUNKLID LAMP	48.00	
4	ZZ/004	APPLY SEALANT TO TRUNKLID	100.00	
5	ZZ/005	PERFORM RUST PROOFING RR END PANEL	120.00	
6	ZZ/006	R/INSTALL BOTH INNER TRIM,TRUNKFLOOR COVER TO FACILITATE REPAIR	240.00	
7	ZZ/007	REMOVE AND TRANSFER TRUNKLID MECHANISM	80.00	
8	ZZ/008	RENEW REVERSE SENSOR	110.00	
TOTAL LABOUR CHARGES			5378.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJV8095P

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMAR
1	SENSOR-REVERSE	SENSOR			250.00
2	EMBLEM SYLPHY	84895-EW000	127.10		
3	EMBLEM NISSAN	84890-EW000	55.70		
4	PLATE-LUGGAGE REAR GARNISH	84921-EW01A	280.20		
5	LH TRUNKLID HINGE	84401-EW000	45.60		
6	RH TRUNKLID HINGE	84400-EW000	45.60		
7	TRUNKLID LOCK	84631-EW000	150.70		
8	REAR LICENCE PLATE	RLP			60.00
9	TRUNKLID TOP CHROME MOULDING	84810-EW005	362.80		
10	TRUNK LID LOWER CHRME MLDG	84860-EW000	207.00		
11	WSTRIP-TRUNK LID	84830-EW000	124.60		
12	TRUNK LID	H430M-EX1MA	1202.10		
13	SUNDRIES	NPN			50.00
14	LH SIDE BRACKET RR BUMPER	85227-EW000	52.40		
15	RH SIDE BRACKET RR BUMPER	85226-EW000	52.40		
16	STAY-REAR BUMPER @SGD\$54.00 EACH	85212-AX010	108.00		
17	CLIP RR BUMPER @ SGD\$1.50 EACH	01553-10501	15.00		
18	CHROME MOULDING RR BUMPER	85072-EW000	233.40		
19	REAR BUMPER	85022-EW025	939.40		
SUB TOTAL			4002.00	0.00	360.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			800.40	0.00	0.00
GRAND TOTAL			3201.60	0.00	360.00
OVERALL TOTAL			3561.60		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJV8095P

TOTAL LABOUR CHARGES	5378.00
TOTAL SPARE PARTS CHARGES	3561.60

GRAND TOTAL	8939.60 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.