

Date: 26-11-2024

Vehicle No: SNC1000L

Model: Tesla Model 3

Chassis: LRW3F7FA0MC384528

Reg.Year: 18.11.2021

NOT NOTED
Runny B& pain
3 day

Third Party Insurer: AIG

Third Party Veh No: SMQ6416B

Date of Accident: 22/9/2024

Estimator: Loong

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	<i>mg 1.27</i>	\$766.00
2	REAR RH BUMPER RETAINER	1		<i>Re</i> \$7.47
3	REAR REVERSE SENSOR	1		<i>Re</i> \$163.55
4	REAR RH WHEEL RIM COVER	1		<i>Re</i> \$32.40
5	REAR RH FENDER PANEL OUTER	1		REPAIR
SUB TOTAL				\$969.42
LESS 10%				-\$96.94
PARTS TOTAL				\$872.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>na</i> \$50.00
2	REAR BUMPER LOWER CLIPS	1		<i>na</i> \$50.00
S/N TOTAL				\$100.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR RH FENDER PANEL & ETC.

\$600.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$100.00

LABOUR TOTAL \$1,500.00

TOTAL \$2,472.48

Finalise:
Parts \$ 689.40
Nett = \$ 50.00
Labour \$ 850.00

Pay by Pay 1549.40
1589.40