

ASS. REC. BY:

REF:

C721 CS/CTI 2411606/Kvh3 Authorize 17/2/25

Hennrich

## ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

SNM24D206641

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Soon:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNW 43306 Yr Regn: 12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.


L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time

Action / Instruction

29/11

Report to Cecilia via Email.

① DOA: 31/10/24 right side

② DOA: 3/11/24 HIT TP Rear

NV: 50,947

28/4

812270.00 Only

(red 1196.20, 9%)

Time, File Pass to?



Prell. Report



Final Report

Time, File Return to?

Days Of Repair: 7

Resurvey No. of Trip:

Survey Fee:

Transportation

S - R.S. - SI

Fees

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Format:

Sum / I.B.I: (\$

Back to OneMotoring

**Inquire PARF/COE Rebate for Registered Vehicle**  
**Vehicle Owner Particulars**

|                               |                                |
|-------------------------------|--------------------------------|
| Owner ID Type:                |                                |
| Owner ID:                     | Company                        |
| Vehicle Details               | 892N                           |
| Vehicle No.:                  |                                |
| Vehicle to be Exported:       | SNN4330G                       |
| Intended Deregistration Date: | No                             |
| Vehicle Make:                 | 25 Nov 2024                    |
| Vehicle Model:                | MERCEDES BENZ                  |
| Primary Colour:               | A200 SPORT EXECUTIVE AUTO      |
| Manufacturing Year:           | Black                          |
| Engine No.:                   | 2021                           |
| Chassis No.:                  | 28291480668338                 |
| Maximum Power Output:         | W1K1771872J322427              |
| Open Market Value:            | 120.0 kW (160 bhp)             |
| Original Registration Date:   | \$31,281.00                    |
| First Registration Date:      | 07 Dec 2023                    |
| Transfer Count:               | 07 Dec 2023                    |
| Actual ARF Paid:              | 0                              |
| Intended PARF Rebate Details  | \$35,794.00                    |
| PARF Eligibility:             | Yes                            |
| PARF Eligibility Expiry Date: | 06 Dec 2033                    |
| PARF Rebate Amount:           | \$26,845.00                    |
| Intended COE Rebate Details   |                                |
| COE Expiry Date:              | 06 Dec 2033                    |
| COE Category:                 | B - Car-Details at OneMotoring |
| COE Period(Years):            | 10                             |
| QP Paid:                      | \$135,336.00                   |
| COE Rebate Amount:            | \$122,208.00                   |
| <b>Total Rebate Amount:</b>   | <b>\$149,053.00</b>            |

**Message**

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 25 Nov 2024

OK



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM24D206641  
Our ref: CS/CTI24110606/Knh3

Date: 29.11.2024

The Motor Claims Department  
China Taiping Insurance (S) Pte Ltd

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SNN 4330G**


We thank you for your instruction on 28/11/2024

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/11/2024 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd and have the following to report:-

|                          |                  |
|--------------------------|------------------|
| Workshop Estimate Amount | : S\$ 10,617.29  |
| Revised Estimate Amount  | : S\$ 6,721.29   |
| "Check" Items Amount     | : S\$ 3,812.00   |
| Market Value             | : S\$ 200,000.00 |
| LTA Reimbursement Value  | : S\$ 149,053.00 |
| Nett Value               | : S\$ 50,947.00  |

**Description of Damage:**

The vehicle sustained damages at the front portion.



**Comments/Present Status:**

Damages Consistent.  
Repair Cost Economical.

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.

Yours faithfully,

Kenneth Kong  
**Licensed Appraiser**

Lai Huat (Meng Kee) Motor Pte Ltd  
160 Sin Ming Drive, #04-01, #04-02 & #07-03,  
Sin Ming Autocity  
575722

Insurer Reference: DMHCSNA00003412400-SNN4330G  
Repairer Reference: 74847  
Date calculated: 28/11/2024 2:15 PM

Full Report  
Registration: SNN4330G  
Printed: 28/11/2024 2:15 PM

### Summary Information

|                        |                             |                   |                                                |
|------------------------|-----------------------------|-------------------|------------------------------------------------|
| <b>Claim</b>           |                             |                   |                                                |
| Location:              | Singapore (SG)              | Work Provider:    | China Taiping Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | Jenny Lim                   | Currency:         | SGD                                            |
| Claim Reference:       | DMHCSNA00003412400-SNN4330G | Date of Incident: | 15/11/24                                       |
| Estimated Repair Time: |                             | Hire Car Start:   |                                                |
| Actual Repair Days:    |                             | Hire Car End:     |                                                |

### Vehicle Details

**Vehicle**  
Manufacturer: MERCEDES-BENZ  
Model: A-CLASS (V177)  
Sub Model: A 200  
Model Sheet Number: 03 AZ 44  
Registration: SNN4330G  
VIN number: W1K1771872J322427  
Odometer: 31321

#### Model Specs

|                      |                       |                      |                      |
|----------------------|-----------------------|----------------------|----------------------|
| FROM VIN J255092     | DYNAMIC SELECT        | SHIFT PADDLE ON STRG | KNEE AIRBAG          |
| HEADLINING BLACK     | MULTI FUNC ST/WHEEL   | RR TORSION BEAM AXLE | MODIFICAT PACK 20/2  |
| MODEL 2021           | DR MIRROR GPS AERIAL  | AIR CON THERMOTRONIC | DAB TUNER            |
| SPEED LIMITER        | RAIN SENSOR           | ACT LANE KEEP ASSIST | ACTIVE BRAKE ASSIST  |
| TRIM CARBON LOOK     | TOUCHPAD              | SMARTPHONE INTEGRAL  | CONNECT 20 MID       |
| CENTRAL DISPLAY      | H-LAMP LED HIGH PER   | LIGHT-/VIEW PACKAGE  | R/BACKREST FOLDABLE  |
| LEATHER/CLOTH UPHOLS | PROGRESSIVE           | DOUBLE CUP HOLDER    | ELEC FOLD DR MIRRORS |
| OUT/IN MIRR AUTO DIM | PASS AIRBAG INTERRUPT | RR S-BELT INDICATOR  | MIRROR PACKAGE       |
| STORAGE BOX          | SEAT COMFORT PACKAGE  | SUN VISOR SPEC FUNC  | EMERGENCY CALL SYS   |
| MOBILE COM-MOD UMTS  | ANTI-THEFT ALARM      | REARVIEW CAMERA      | INCR ANTI THEFT DEV  |
| POWER- YST EURO 6D   | EXH SYS WITH OPF GEN  | RADIATOR SHROUD      | UPPER RADIATOR BLIND |
| CYLINDER MANAGEMENT  | EMISSION STD EURO 6   | TYRE PRESSURE SENSOR | CRUISE CONTROL       |
| 7 SPEED AUTOMATIC    | DIRECT STEERING       | COMFORT SUSPENSION   | INTERIOR PROTECTION  |
| TYRES 205/55 R17..W  | WHEELS 6.5J X 17 ALU  | TECHNO 48V PREPARE   | EURO NCAP COUNTRIES  |
| HEATED FRONT SEATS   | WIRELESS CHARGE SYS   | PEDESTRIAN PROTECT   | ACTIVE PARK-ASSIST   |
| COMPRESSOR VARIABLE  | PARK PACK             | TWO COAT METALLIC    | PREPARE OFF VEHICLE  |
| REFRIGERANT R1234YF  | CLEAR COAT HARD       |                      |                      |

*Not Authorized  
Mummy B6 part  
Ex 82000  
7 days*

### Labour

| Code      | Description | Time Base 10 WU/h | Price = 42.00 SGD/h |           |
|-----------|-------------|-------------------|---------------------|-----------|
|           |             |                   | WU                  | Price SGD |
| 4-1011 01 | SHORT TEST  |                   | 3.0                 | 12.60     |

Insurer Reference: DMHCSNA00003412400-SNN4330G  
 Repairer Reference: 74847  
 Date calculated: 28/11/2024 2:15 PM

Full Report  
 Registration: SNN4330G  
 Printed: 28/11/2024 2:15 PM

| Code                             | Description                                                                                                                                                                                                     | WU           | Price SGD       |
|----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|-----------------|
| 54-7989 01                       | INCLUDES: CONNECT + DISCONNECT STAR<br>DIAGNOSIS,<br>PRINT DATA,<br>DELETE ERROR MEMORY<br>R + R BATTERY EARTH CABLE<br>(WHEN DISCONNECTING ELECTRIC PLUG AND<br>SOCKET CONNECTIONS)                            | 2.0          | 8.40            |
| NO NUMBER<br>88-2532 ZAX         | R + R COMPL LWR ENGINE COMPARTMENT COVER<br>REPAIR OF FRONT-END DAMAGE<br>INCLUDES: RENEW BUMPER, BONNET, RADIATOR<br>COVER, FRONT WINGS AND FRONT LAMP UNITS,<br>CONVERT ATTACHED PARTS, RENEW IF<br>NECESSARY | 5.0<br>36.0  | 21.00<br>151.20 |
| 88-1319 01                       | ADD FOR R + R FRONT BUMPER<br>(VEHICLE WITH PARKTRONIC)                                                                                                                                                         | 1.0          | 4.20            |
| 88-1935 01                       | ADDITION TO R + R FRONT BUMPER<br>(VEHICLE WITH PEDESTRIAN PROTECT)                                                                                                                                             | 1.0          | 4.20            |
| 88-1364 01                       | ADDITION TO DIS + ASS FRONT BUMPER<br>(VEHICLE WITH ACTIVE BRAKE ASSIST)                                                                                                                                        | 1.0          | 4.20            |
| 88-1360 01                       | ADDITION TO DIS + ASS FRONT BUMPER<br>(VEHICLE WITH PARK ASSISTANT)                                                                                                                                             | 3.0          | 12.60           |
| 88-1933 ZAX                      | ADDITION TO R + R FRONT BUMPER<br>(VEHICLE WITH COLLISION WARN SYS)                                                                                                                                             | 1.0          | 4.20            |
| 88-1162 01                       | ADDITION TO DIS + ASS FRONT BUMPER<br>(VEHICLE WITH ACTIVE BRAKE ASSIST)                                                                                                                                        | 1.0          | 4.20            |
| 82-4887 01                       | ADDITIONAL TO RENEW BOTH HEADLAMPS<br>(VEHICLE WITH LED HEADLAMP)                                                                                                                                               | 3.0          | 12.60           |
| 88-2657 01                       | RENEW BOTH BONNET HINGES (REMOVED)                                                                                                                                                                              | 7.0          | 29.40           |
| 60-1331 01                       | ATTACHED PARTS IN ENGINE COMPART R + R<br>FOR RENEWAL OF THE FRONT MODULE<br>INCLUDES: ALL ATTACHED PARTS IN REPAIR<br>AREA REMOVE AND REFIT                                                                    | 10.0         | 42.00           |
| 62-1266 01                       | FRONT CROSS MEMBER AND BRACE BETWEEN<br>THE WHEELHOUSES COMPLETE R + R                                                                                                                                          | 14.0         | 58.80           |
| 62-1290 01                       | R + R L/F BUMPER ABSORBER                                                                                                                                                                                       | 3.0          | 12.60           |
| NO NUMBER                        | R + R CHARGE AIR DISTRIBUTING PIPE                                                                                                                                                                              | 11.0         | 46.20           |
| NO NUMBER                        | RENEW CHARGE AIR DISTRIBUTING PIPE (REM)                                                                                                                                                                        | 2.0          | 8.40            |
| 60-1234 01)                      | R + R RADIATOR                                                                                                                                                                                                  | 3.0          | 12.60           |
| 20-4000 01)                      | RENEW RADIATOR (REMOVED)                                                                                                                                                                                        | 1.0          | 4.20            |
| 20-6461 01                       | R + R FAN UNIT                                                                                                                                                                                                  | 4.0          | 16.80           |
| 83-6543 01)                      | R + R CONDENSER                                                                                                                                                                                                 | 14.0         | 58.80           |
| 83-1762 01                       | AIR-CONDITIONING SYSTEM DRAIN FLUID,<br>EXHAUST, REFILL, PRESSURE TEST<br>(FOR ALL WORK ON THE SYSTEM)                                                                                                          | 6.0          | 25.20           |
| 82-1120 01                       | ADJUST LED HEADLAMP                                                                                                                                                                                             | 7.0          | 29.40           |
| 1481                             | LEFT FRONT DOOR REPAIR                                                                                                                                                                                          | nn 20.0* X   | 84.00           |
| <b>Labour Cost</b>               |                                                                                                                                                                                                                 | <b>Hrs</b>   | <b>WU</b>       |
| <b>Panel / Mechanical Labour</b> |                                                                                                                                                                                                                 | <b>15.90</b> | <b>159.0</b>    |
| <b>Total of Labour</b>           |                                                                                                                                                                                                                 |              | <b>667.80</b>   |

Reference: DMHCSNA00003412400-SNN4330G  
Repairer Reference: 74847  
Date calculated: 28/11/2024 2:15 PM

Full Report  
Registration: SNN4330G  
Printed: 28/11/2024 2:15 PM

### Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code

Description - TWO COAT METALLIC

WU Price SGD

|                                      |      |
|--------------------------------------|------|
| BONNET NEW PART PAINTING             | 25.0 |
| L/F HINGE NEW PART PAINTING          | 5.0  |
| R/F HINGE NEW PART PAINTING          | 5.0  |
| L/F WING NEW PART PAINTING           | 9.0  |
| R/F WING NEW PART PAINTING           | 9.0  |
| FRONT BUMPER TRIM NEW PART PAINT K1R | 14.0 |
| LEFT FRONT DOOR REPAIR PAINTING <50% | 17.0 |
| L/F BUMP IMPACT DAMP SURFACE PAINT   | 4.0  |

### Paint Material Per Part

Code

Description

Price SGD

|      |                                      |       |
|------|--------------------------------------|-------|
| 0471 | BONNET NEW PART PAINTING             | 84.11 |
| 0475 | L/F HINGE NEW PART PAINTING          | 0.52  |
| 0476 | R/F HINGE NEW PART PAINTING          | 0.52  |
| 0741 | L/F WING NEW PART PAINTING           | 16.51 |
| 0742 | R/F WING NEW PART PAINTING           | 16.51 |
| 0283 | FRONT BUMPER TRIM NEW PART PAINT K1R | 71.83 |
| 1481 | LEFT FRONT DOOR REPAIR PAINTING <50% | 30.04 |
| 1007 | L/F BUMP IMPACT DAMP SURFACE PAINT   | 1.25  |

### Labour Cost - Paint

Factor

42.00 SGD/h

Hrs

WU Price SGD

Time Paint

88.0

Preparation Main Work Metal

2.50

25.0

105.00

Preparation Comp. Work Plastic

0.50

5.0

21.00

Total

10 WU/h

11.80

118.0

495.60

### Material Cost - Paint

New Part Painting

Price SGD

118.17

New Part Painting - Plastic K1R

71.83

Repair Painting

30.04

Surface-/Blend Paint

1.25

Material-constant Metal Preparation

28.60

Material-constant Plastic

9.00

Total

258.89

### Spare Parts

Code

Description

Part Number

Part Source

prices as at 2015-06-01

Price SGD

|      |                   |              |          |               |
|------|-------------------|--------------|----------|---------------|
| 4465 | AIR CON CONDENSER | 247 500 0054 | Original | Pac 590.00 ✓  |
| 1001 | AIR DISTR SEAL    | 282 098 0400 | Original | Dir ✓ 48.00 ✓ |
| 8391 | AIR FILTER ASSY   | 282 090 3800 | Original | CM ✓ 205.00 ✓ |
| 8385 | AIR INTAKE HOSE   | 654 094 3400 | Original | CM ✓ 210.00 ✓ |
| 0471 | BONNET            | 177 880 1800 | Original | R ✓ 835.00 ✓  |
| 0930 | CTR FRT REINF     | 177 620 8000 | Original | A ✓ 390.00 ✓  |

Audatex System Using Manufacturer Times

Page 3 of 5

PRINT DATE 28/11/2024

| Code                     | Description          | Part Number       | Part Source | Price SGD       |
|--------------------------|----------------------|-------------------|-------------|-----------------|
| 0283                     | FRONT BUMPER TRIM    | 177 880 4200 9999 | Original    | CM ✓ 640.00 ✓   |
| 1001                     | FRONT CROSSMEMBER    | 177 620 4901      | Original    | R 245.00 ✓      |
| 0405                     | FRONT GRILLE         | 177 880 5703      | Original    | CM ✓ 450.00 ✓   |
| 0336                     | FRONT IMPACT DAMPER  | 177 885 9402      | Original    | SR ✓ 95.00 ✓    |
| 7779                     | FRT AIR GUIDE GRILLE | 177 885 4700      | Original    | CM ✓ 70.00 ✓    |
| 0340                     | FRT BUMPER C-MEMBER  | 177 885 1300      | Original    | CM ✓ 100.00 ✓   |
| 7789                     | HEATER BLOWER        | 247 906 7906      | Original    | CM ✓ 460.00 ✓   |
| 8221                     | INTAKE MANIFOLD      | 282 140 2000      | Original    | CM ✓ 350.00 ✓   |
| 8169                     | INT MANIFOLD FLANGE  | 282 098 1200      | Original    | DI ✓ 60.00 ✓    |
| 1007                     | L/F BUMP IMPACT DAMP | 177 620 2300      | Original    | DI ✓ 80.00 ✓    |
| 0475                     | L/F HINGE            | 177 880 1100      | Original    | DI ✓ 45.00 ✓    |
| 0315                     | L/F INN BUMPER BRKT  | 177 885 1700      | Original    | DI ✓ 14.00 ✓    |
| 0359                     | L/F INN SPACER RING  | 000 542 1251      | Original    | DI ✓ 0.00 ✓     |
| 0841                     | L/F W-HOUSE FRT CVR  | 177 690 0104      | Original    | DI ✓ 135.00 ✓   |
| 0839                     | L/F W-HOUSE INN CVR  | 177 884 0700      | Original    | DI ✓ 20.00 ✓    |
| 0843                     | L/F W-HOUSE RR COVER | 247 690 6500      | Original    | DI ✓ 128.00 ✓   |
| 0741                     | L/F WING             | 177 881 0500      | Original    | DI ✓ 410.00 ✓   |
| 0561                     | LEFT HEADLAMP ASSY   | 177 906 0301      | Original    | DI ✓ 1,650.00 ✓ |
| 1003                     | MANIFOLD GASKET      | 282 098 0300      | Original    | DI ✓ 48.00 ✓    |
| 0476                     | R/F HINGE            | 177 880 1200      | Original    | DI ✓ 45.00 ✓    |
| 0360                     | R/F INN SPACER RING  | 000 542 1251      | Original    | DI ✓ 0.00 ✓     |
| 0742                     | R/F WING             | 177 881 0600      | Original    | DI ✓ 410.00 ✓   |
| 0437                     | RAD GRILLE COVER     | 177 888 0300 9982 | Original    | DI ✓ 150.00 ✓   |
| 7761                     | RADIATOR             | 247 500 0203 68   | Original    | DI ✓ 700.00 ✓   |
| 7775                     | RADIATOR ACTUATOR    | 177 500 7900      | Original    | DI ✓ 170.00 ✓   |
| 0432                     | STAR EMBLEM          | 000 817 6203      | Original    | DI ✓ 45.00 ✓    |
| 0433                     | STAR EMBLEM          | 000 817 1001      | Original    | DI ✓ 90.00 ✓    |
| 1002                     | THROTTLE BODY        | 282 098 0200      | Original    | DI ✓ 12.00 ✓    |
| 9634                     | GASKET               |                   |             | CM ✓ 25.00 ✓    |
|                          | UPPER BATTERY COVER  | 247 540 0025      | Original    |                 |
| Savings                  |                      |                   |             | 0.00            |
| Subtotal                 |                      |                   |             | 8,925.00        |
| Fixed Sundry Parts Price |                      |                   |             | 100.00          |
| Total                    |                      |                   |             | 9,025.00        |

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

#### Extras

| Code         | Description                       | Price SGD |
|--------------|-----------------------------------|-----------|
| 1000         | CHK/CLEAR FAULT CODE AFTER REPAIR | ✓ 120.00* |
| 1004         | AIRCON GAS                        | ✓ 50.00*  |
| Total Extras |                                   | 170.00    |

Reference: DMHCSNA00003412400-SNN4330G  
Repairer Reference: 74847  
Date calculated: 28/11/2024 2:15 PM

Full Report  
Registration: SNN4330G  
Printed: 28/11/2024 2:15 PM

| Final Calculation                         | SGD       | SGD       |
|-------------------------------------------|-----------|-----------|
| <b>Parts</b>                              | 8,925.00  |           |
| Fixed Sundry Parts Price                  | 100.00    | 9,025.00  |
| <b>Total Parts</b>                        |           |           |
| <b>Labour Time Base 10 WU/h</b>           | 667.80    | 663.60    |
| Total 159.0 WU X 42.00 SGD/h              | 583.80    | 667.80    |
| <b>Total of Labour</b>                    |           | 170.00✓   |
| <b>Total Of Extras</b>                    |           |           |
| <b>Paint Work Time Base 10 WU/h</b>       | 495.60    | ✓         |
| Labour Cost 118.0 WU X 42.00 SGD/h        | 258.89    | ✓         |
| Material Cost                             |           | 754.49✓   |
| <b>Total Paint Including Material</b>     |           |           |
| <b>Repair Cost Excludes GST</b>           |           | 10,617.29 |
| GST (+9.00%)                              |           | 955.56    |
| <b>Repair Cost Included GST</b>           |           | 11,572.85 |
| <b>Deductions (Excludes GST)</b>          |           |           |
| Deduction For Excess                      | -2,000.00 | -2,000.00 |
| <b>Total Of Deductions (Excludes GST)</b> |           |           |
| <b>Grand Total Excludes GST</b>           |           | 8,617.29  |
| GST (+9.00%)                              |           | 775.56    |
| <b>Grand Total Included GST</b>           |           | 9,392.85  |

#### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

#### Assessment Note

No assessment notes entered.

来發 (明記) 摩哆有限公司  
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No ..... EST0036251  
China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Page ..... 1 of 1  
Your ref ..... DMHCSNA00003412400  
Job No ..... 74847  
Our ref ..... 24.11.26  
Payment ..... 19/3/2025  
Date .....

Attn .....

Vehicle No ..... SNN 4330G  
Vehicle Model : Mercedes Benz A200  
Accident on ... 15/11/2024

| Quantity             | Unit | Description               | Unit price | Disc. pct. | Amount   |
|----------------------|------|---------------------------|------------|------------|----------|
| SUPPLEMENTARY ITEMS. |      |                           |            |            |          |
|                      |      |                           | 20.00      |            | 20.00    |
| 1.00                 | Pc   | LEFT BONNET STOP          | 90.00      |            | 90.00    |
| 1.00                 | Pc   | INTAKE AIR SENSOR         | 1,690.00   |            | 1,690.00 |
| 1.00                 | Pc   | RIGHT HEADLAMP ASSY       | 30.00      |            | 30.00    |
| 1.00                 | Pc   | INT AIR TEMP SENSOR       | 170.00     |            | 170.00   |
| 1.00                 | Pc   | INTAKE PIPE               | 45.00      |            | 45.00    |
| 1.00                 | Pc   | L/SIDE SKIRT              | 38.00      |            | 38.00    |
| 1.00                 | Pc   | RADIATOR AIR GUIDE        | 26.00      |            | 26.00    |
| 1.00                 | Pc   | SPRING ELEMENT            | 128.00     |            | 128.00   |
| 1.00                 | Pc   | WASHER CONTAINER          | 50.00      |            | 50.00    |
| 1.00                 | Pc   | WASHER JET HOSE           | 280.00     |            | 280.00   |
| 1.00                 | Pc   | L/H-LAMP REG C-UNIT       | 35.00      |            | 35.00    |
| 1.00                 | Pc   | L/GRILLE TRIM             | 35.00      |            | 35.00    |
| 1.00                 | Pc   | R/GRILLE TRIM             | 65.00      |            | 65.00    |
| 1.00                 | Pc   | L/F UPP BUMPER BRKT       | 115.00     |            | 115.00   |
| 1.00                 | Pc   | BATTERY                   | 16.00      |            | 16.00    |
| 2.00                 | Pcs  | FRONT SUPPORT PANEL MOUNT |            |            | 32.00    |

Sub-Total 2,849.00  
GST 9.00% 256.41  
Total S\$ 3,105.41

司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。  
还有先进的 SAICO Deluxe 喷漆烘炉。  
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO e oven heater for re-spraying all motor vehicles."

**Veron Chen (LKKAUTO)**

---

**From:** Jenny Lim <jenny.lim@laihuat.com.sg>  
**Sent:** Friday, 11 April 2025 11:38 AM  
**To:** Kenneth Kong (LKKAUTO)  
**Cc:** SUR  
**Subject:** Finalisation-SNN 4330G / Mercedes Benz A200 DOA: 15.11.2024  
**Attachments:** SNN4330G-Audatex Estimate.pdf; SNN 4330G-Supplier Bills.pdf; IMG-20250324-WA0013.jpg; IMG-20250324-WA0014.jpg; IMG-20250324-WA0018.jpg; IMG-20250324-WA0019.jpg; IMG-20250324-WA0354.jpg; IMG-20250324-WA0356.jpg; IMG-20250324-WA0357.jpg; IMG-20250324-WA0358.jpg; LH SNN4330G BEFORE.pdf; LH SNN4330G DONE.pdf

Dear Sir

For your confirmation, please:

- Parts: \$10,582.00
- %: -
- SN: \$270.00 (include Sundry)
- L&M: \$1,502.09
- Sub-total: \$12,354.09
- Less XC: \$2,000.00
- Total: \$10,354.09
- No of days: -

Supporting documents and photographs are enclosed for your reference.

We look forward to hearing from you soon.

Thank you.

Kind regards.

Jenny Lim  
Lai Huat (Meng Kee) Motor Pte Ltd  
160 Sin Ming Drive  
#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110 Fax: 64596267

**Lai Huat (Meng Kee) Motor Pte Ltd**  
**160 Sin Ming Drive, #04-01, #04-02 & #07-03,**  
**Sin Ming Autocity**  
**575722**

**Insurer Reference: DMHCSNA00003412400-SNN4330G**

**Repairer Reference: 74847**

**Date calculated: 11/04/2025 11:25 AM**

**Full Report**

**Registration: SNN4330G**

**Printed: 11/04/2025 11:25 AM**

### Summary Information

#### Claim

|                        |                             |                   |                                                |
|------------------------|-----------------------------|-------------------|------------------------------------------------|
| Location:              | Singapore (SG)              | Work Provider:    | China Taiping Insurance<br>(Singapore) Pte Ltd |
| Printed by:            | Jenny Lim                   | Currency:         | SGD                                            |
| Claim Reference:       | DMHCSNA00003412400-SNN4330G | Date of Incident: | 15/11/24                                       |
| Estimated Repair Time: |                             | Hire Car Start:   |                                                |
| Actual Repair Days:    |                             | Hire Car End:     |                                                |

### Vehicle Details

#### Vehicle

|                     |                   |
|---------------------|-------------------|
| Manufacturer:       | MERCEDES-BENZ     |
| Model:              | A-CLASS (V177)    |
| Sub Model:          | A 200             |
| Model Sheet Number: | 03 AZ 44          |
| Registration:       | SNN4330G          |
| VIN number:         | W1K1771872J322427 |
| Odometer:           | 31321             |

#### Model Specs

|                      |                       |                      |                      |
|----------------------|-----------------------|----------------------|----------------------|
| FROM VIN J255092     | DYNAMIC SELECT        | SHIFT PADDLE ON STRG | KNEE AIRBAG          |
| HEADLINING BLACK     | MULTI FUNC ST/WHEEL   | RR TORSION BEAM AXLE | MODIFICAT PACK 20/2  |
| MODEL 2021           | DR MIRROR GPS AERIAL  | AIR CON THERMOTRONIC | DAB TUNER            |
| SPEED LIMITER        | RAIN SENSOR           | ACT LANE KEEP ASSIST | ACTIVE BRAKE ASSIST  |
| TRIM CARBON LOOK     | TOUCHPAD              | SMARTPHONE INTEGRAL  | CONNECT 20 MID       |
| CENTRAL DISPLAY      | H-LAMP LED HIGH PER   | LIGHT-/VIEW PACKAGE  | R/BACKREST FOLDABLE  |
| LEATHER/CLOTH UPHOLS | PROGRESSIVE           | DOUBLE CUP HOLDER    | ELEC FOLD DR MIRRORS |
| OUT/IN MIRR AUTO DIM | PASS AIRBAG INTERRUPT | RR S-BELT INDICATOR  | MIRROR PACKAGE       |
| STORAGE BOX          | SEAT COMFORT PACKAGE  | SUN VISOR SPEC FUNC  | EMERGENCY CALL SYS   |
| MOBILE COM-MOD UMTS  | ANTI-THEFT ALARM      | REARVIEW CAMERA      | INCR ANTI THEFT DEV  |
| POWER- YST EURO 6D   | EXH SYS WITH OPF GEN  | RADIATOR SHROUD      | UPPER RADIATOR BLIND |
| CYLINDER MANAGEMENT  | EMISSION STD EURO 6   | TYRE PRESSURE SENSOR | CRUISE CONTROL       |
| 7 SPEED AUTOMATIC    | DIRECT STEERING       | COMFORT SUSPENSION   | INTERIOR PROTECTION  |
| TYRES 205/55 R17..W  | WHEELS 6.5J X 17 ALU  | TECHNO 48V PREPARE   | EURO NCAP COUNTRIES  |
| HEATED FRONT SEATS   | WIRELESS CHARGE SYS   | PEDESTRIAN PROTECT   | ACTIVE PARK-ASSIST   |
| COMPRESSOR VARIABLE  | PARK PACK             | TWO COAT METALLIC    | PREPARE OFF VEHICLE  |
| REFRIGERANT R1234YF  | CLEAR COAT HARD       |                      |                      |

### Labour

| Code       | Description | Time Base 10 WU/h | Price = 42.00 SGD/h |           |
|------------|-------------|-------------------|---------------------|-----------|
|            |             |                   | WU                  | Price SGD |
| 54-1011 01 | SHORT TEST  |                   | 3.0                 | 12.60     |

Insurer Reference: DMHCSNA00003412400-SNN4330G  
 Repairer Reference: 74847  
 Date calculated: 11/04/2025 11:25 AM

Full Report  
 Registration: SNN4330G  
 Printed: 11/04/2025 11:25 AM

| Code        | Description                                                                                                                                                         | WU      | Price SGD |
|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|-----------|
|             | INCLUDES: CONNECT + DISCONNECT STAR<br>DIAGNOSIS,<br>PRINT DATA,<br>DELETE ERROR MEMORY                                                                             |         |           |
| 61-1071 01  | R + R FRONT LOWER ENGINE COMPARTMENT<br>COVER                                                                                                                       | 4.0     | 16.80     |
| 88-2532 ZAX | REPAIR OF FRONT-END DAMAGE<br>INCLUDES: RENEW BUMPER, BONNET, RADIATOR<br>COVER, FRONT WINGS AND FRONT LAMP UNITS,<br>CONVERT ATTACHED PARTS, RENEW IF<br>NECESSARY | 36.0    | 151.20    |
| 88-1319 01  | ADD FOR R + R FRONT BUMPER<br>(VEHICLE WITH PARKTRONIC)                                                                                                             | 1.0     | 4.20      |
| 88-1935 01  | ADDITION TO R + R FRONT BUMPER<br>(VEHICLE WITH PEDESTRIAN PROTECT)                                                                                                 | 1.0     | 4.20      |
| 88-1364 01  | ADDITION TO DIS + ASS FRONT BUMPER<br>(VEHICLE WITH ACTIVE BRAKE ASSIST)                                                                                            | 1.0     | 4.20      |
| 88-1360 01  | ADDITION TO DIS + ASS FRONT BUMPER<br>(VEHICLE WITH PARK ASSISTANT)                                                                                                 | 3.0     | 12.60     |
| 88-1933 ZAX | ADDITION TO R + R FRONT BUMPER<br>(VEHICLE WITH COLLISION WARN SYS)                                                                                                 | 1.0     | 4.20      |
| 88-1162 01  | ADDITION TO DIS + ASS FRONT BUMPER<br>(VEHICLE WITH ACTIVE BRAKE ASSIST)                                                                                            | 1.0     | 4.20      |
| 82-4887 01  | ADDITIONAL TO RENEW BOTH HEADLAMPS<br>(VEHICLE WITH LED HEADLAMP)                                                                                                   | 3.0     | 12.60     |
| 88-2657 01  | RENEW BOTH BONNET HINGES (REMOVED)                                                                                                                                  | 7.0     | 29.40     |
| 60-1331 01  | ATTACHED PARTS IN ENGINE COMPART R + R<br>FOR RENEWAL OF THE FRONT MODULE<br>INCLUDES: ALL ATTACHED PARTS IN REPAIR<br>AREA REMOVE AND REFIT                        | 10.0    | 42.00     |
| 62-1279 01  | REPLACE INTEGRAL CARRIER (STRIPPED)<br>INCLUDES: STRUT BETWEEN INTEGRAL CARR-<br>IER AND RADIATOR CARRIER R + R                                                     | 9.0     | 37.80     |
| 62-1290 01  | R + R L/F BUMPER ABSORBER                                                                                                                                           | 3.0     | 12.60     |
| 82-7351 01) | R + R HEADLAMP WASHER WIRING HARNESS                                                                                                                                | 5.0     | 21.00     |
| 54-1126 01  | RENEW BATTERY                                                                                                                                                       | 8.0     | 33.60     |
| 88-9930 01  | R + R L/DRIP MOULDING                                                                                                                                               | 3.0     | 12.60     |
| 09-8400 02  | R + R ENGINE SUCTION AIR CHANNEL<br>(BEHIND AIR FILTER)                                                                                                             | 8.0     | 33.60     |
| 09-6955 01  | R + R INTAKE AIR SENSOR                                                                                                                                             | 3.0     | 12.60     |
| NO NUMBER   | R + R CHARGE AIR DISTRIBUTING PIPE                                                                                                                                  | 11.0    | 46.20     |
| NO NUMBER   | RENEW CHARGE AIR DISTRIBUTING PIPE (REM)                                                                                                                            | 2.0     | 8.40      |
| 20-6461 01  | R + R FAN UNIT                                                                                                                                                      | 4.0     | 16.80     |
| NO NUMBER   | R + R FRONT AIR GUIDE                                                                                                                                               | 3.0     | 12.60     |
| 83-6543 01) | R + R CONDENSER                                                                                                                                                     | 14.0    | 58.80     |
| 40-1470 01  | ADD TO R/F WHEEL REMOVE AND REFIT<br>(ASSEMBLY ON WHEELS FROM 17 INCH                                                                                               | 1.0     | 4.20      |
| 83-1762 01  | AIR-CONDITIONING SYSTEM DRAIN FLUID,<br>EXHAUST, REFILL, PRESSURE TEST<br>(FOR ALL WORK ON THE SYSTEM)                                                              | 6.0     | 25.20     |
| 82-1120 01  | ADJUST LED HEADLAMP                                                                                                                                                 | 7.0     | 29.40     |
| 1481        | LEFT FRONT DOOR REPAIR                                                                                                                                              | ~ 20.0* | 84.00 X   |

Insurer Reference: DMHCSNA00003412400-SNN4330G  
 Repairer Reference: 74847  
 Date calculated: 11/04/2025 11:25 AM

Full Report  
 Registration: SNN4330G  
 Printed: 11/04/2025 11:25 AM

|                                  |              |              |               |
|----------------------------------|--------------|--------------|---------------|
| <b>Labour Cost</b>               | <b>Hrs</b>   | <b>WU</b>    |               |
| <b>Panel / Mechanical Labour</b> | <b>17.80</b> | <b>178.0</b> | <b>747.60</b> |
| <b>Total of Labour</b>           |              |              | <b>747.60</b> |

## Paint

| Paint Work | SYSTEM AZT                           | Time Basis 10 WU/h |
|------------|--------------------------------------|--------------------|
| Code       | Description - TWO COAT METALLIC      | WU Price SGD       |
|            | BONNET NEW PART PAINTING             | 25.0               |
|            | L/F HINGE NEW PART PAINTING          | 5.0                |
|            | R/F HINGE NEW PART PAINTING          | 5.0                |
|            | L/F WING NEW PART PAINTING           | 9.0                |
|            | R/F WING NEW PART PAINTING           | 9.0                |
|            | FRONT BUMPER TRIM NEW PART PAINT K1R | 14.0               |
|            | LEFT FRONT DOOR REPAIR PAINTING <50% | 17.0               |
|            | L/F BUMP IMPACT DAMP SURFACE PAINT   | 4.0                |

## Paint Material Per Part

| Code | Description                          | Price SGD |
|------|--------------------------------------|-----------|
| 0471 | BONNET NEW PART PAINTING             | 84.11     |
| 0475 | L/F HINGE NEW PART PAINTING          | 0.52      |
| 0476 | R/F HINGE NEW PART PAINTING          | 0.52      |
| 0741 | L/F WING NEW PART PAINTING           | 16.51     |
| 0742 | R/F WING NEW PART PAINTING           | 16.51     |
| 0283 | FRONT BUMPER TRIM NEW PART PAINT K1R | 71.83     |
| 1481 | LEFT FRONT DOOR REPAIR PAINTING <50% | 30.04     |
| 1007 | L/F BUMP IMPACT DAMP SURFACE PAINT   | 1.25      |

|                                |                |              |                  |
|--------------------------------|----------------|--------------|------------------|
| <b>Labour Cost - Paint</b>     | <b>Hrs</b>     | <b>WU</b>    | <b>Price SGD</b> |
| Factor                         | 42.00 SGD/h    |              |                  |
| Time Paint                     |                | 88.0         |                  |
| Preparation Main Work Metal    | 2.50           | 25.0         | 105.00           |
| Preparation Comp. Work Plastic | 0.50           | 5.0          | 21.00            |
| <b>Total</b>                   | <b>10 WU/h</b> | <b>11.80</b> | <b>118.0</b>     |

|                                     |                  |
|-------------------------------------|------------------|
| <b>Material Cost - Paint</b>        | <b>Price SGD</b> |
| New Part Painting                   | 118.17           |
| New Part Painting - Plastic K1R     | 71.83            |
| Repair Painting                     | 30.04            |
| Surface-/Blend Paint                | 1.25             |
| Material-constant Metal Preparation | 28.60            |
| Material-constant Plastic           | 9.00             |
| <b>Total</b>                        | <b>258.89</b>    |

## Spare Parts

| Code | Description       | Part Number  | Part Source | prices as at 2015-06-01<br>Price SGD |
|------|-------------------|--------------|-------------|--------------------------------------|
| 4465 | AIR CON CONDENSER | 247 500 0054 | Original    | 590.00                               |
| 1001 | AIR DISTR SEAL    | 282 098 0400 | Original    | 48.00                                |

Insurer Reference: DMHCSNA00003412400-SNN4330G  
 Repairer Reference: 74847  
 Date calculated: 11/04/2025 11:25 AM

Full Report  
 Registration: SNN4330G  
 Printed: 11/04/2025 11:25 AM

| Code | Description          | Part Number       | Part Source   | Price SGD |
|------|----------------------|-------------------|---------------|-----------|
| 8391 | AIR FILTER ASSY      | 282 090 3800      | Original      | 205.00    |
| 8385 | AIR INTAKE HOSE      | 654 094 3400      | Original      | 210.00    |
| 9629 | BATTERY              | 001 982 8108 26   | Supplementary | 115.00    |
| 0471 | BONNET               | 177 880 1800      | Original      | 835.00    |
| 0930 | CTR FRT REINF        | 177 620 8000      | Original      | 390.00    |
| 0283 | FRONT BUMPER TRIM    | 177 880           | Original      | 640.00    |
|      |                      | 4200649999        |               |           |
| 0405 | FRONT GRILLE         | 177 880 5703      | Original      | 450.00    |
| 0431 | FRONT STAR EMBLEM    | 177 888 4200      | Original      | 90.00     |
| 1005 | FRONT SUPPORT PANEL  | MOUNT (X2)        | Supplementary | 32.00     |
| 7779 | FRT AIR GUIDE GRILLE | 177 885 4700      | Original      | 70.00     |
| 0340 | FRT BUMPER C-MEMBER  | 177 885 1300      | Original      | 100.00    |
| 7789 | HEATER BLOWER        | 247 906 7906      | Original      | 460.00    |
| 1006 | INT AIR TEMP SENSOR  | 276 905 0000      | Supplementary | 30.00     |
| 8498 | INTAKE AIR SENSOR    | 008 153 4428      | Supplementary | 90.00     |
| 8221 | INTAKE MANIFOLD      | 282 140 2000      | Original      | 350.00    |
| 8382 | INTAKE PIPE          | 282 090 9400      | Supplementary | 170.00    |
| 8169 | INT MANIFOLD FLANGE  | 282 098 1200      | Original      | 60.00     |
| 0303 | L/F BUMPER GRILLE    | 177 885 3100      | Supplementary | 35.00     |
| 1007 | L/F BUMP IMPACT DAMP | 177 620 2300      | Original      | 80.00     |
| 0475 | L/F HINGE            | 177 880 1100      | Original      | 45.00     |
| 0359 | L/F INN SPACER RING  | 000 542 1251      |               | 0.00      |
| 0341 | L/F UPP BUMPER BRKT  | 177 885 9502      | Supplementary | 65.00     |
| 0841 | L/F W-HOUSE FRT CVR  | 177 690 0104      | Original      | 136.00    |
| 0741 | L/F WING             | 177 881 0500      | Original      | 410.00    |
| 9649 | L/H-LAMP REG C-UNIT  | 213 900 2734      | Supplementary | 280.00    |
| 0763 | L/OUTER INTERM PIECE | 177 885 1500      | Original      | 14.00     |
| 2431 | L/SIDE SKIRT         | 177 690 3301 64   | Supplementary | 45.00     |
| 0531 | LEFT BONNET STOP     | 001 998 2740      | Supplementary | 20.00     |
| 0561 | LEFT HEADLAMP ASSY   | 177 906 0301      | Original      | 1,690.00  |
| 1003 | MANIFOLD GASKET      | 282 098 0300      | Original      | 48.00     |
| 0304 | R/F BUMPER GRILLE    | 177 885 3200      | Supplementary | 35.00     |
| 0476 | R/F HINGE            | 177 880 1200      | Original      | 45.00     |
| 0360 | R/F INN SPACER RING  | 000 542 1251      |               | 0.00      |
| 0742 | R/F WING             | 177 881 0600      | Original      | 410.00    |
| 0437 | RAD GRILLE COVER     | 177 888 0300 9982 | Original      | 150.00    |
| 7775 | RADIATOR ACTUATOR    | 177 500 7900      | Original      | 170.00    |
| 7753 | RADIATOR AIR GUIDE   | 177 505 0000      | Supplementary | 38.00     |
| 0562 | RIGHT HEADLAMP ASSY  | 177 906 0401      | Supplementary | 1,690.00  |
| 0523 | SPRING ELEMENT       | 177 880 3100      | Supplementary | 26.00     |
| 1002 | THROTTLE BODY        | 282 098 0200      | Original      | 12.00     |
|      | GASKET               |                   |               |           |
| 9634 | UPPER BATTERY COVER  | 247 540 0025      | Original      | 25.00     |
| 1436 | WASHER CONTAINER     | 177 869 0100      | Supplementary | 128.00    |
| 1445 | WASHER JET HOSE      | 177 860 0100      | Supplementary | 50.00     |

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

**Savings** 0.00  
**Subtotal** 10,582.00  
**Fixed Sundry Parts Price** 100.00  
**Total** 10,682.00

## Extras

| Code | Description                       | Price SGD |
|------|-----------------------------------|-----------|
| 1000 | CHK/CLEAR FAULT CODE AFTER REPAIR | 120.00*   |

Insurer Reference: DMHCSNA00003412400-SNN4330G  
Repairer Reference: 74847  
Date calculated: 11/04/2025 11:25 AM

Full Report  
Registration: SNN4330G  
Printed: 11/04/2025 11:25 AM

| Code | Description         | Price SGD     |
|------|---------------------|---------------|
| 1004 | AIRCON GAS          | 50.00*        |
|      | <b>Total Extras</b> | <b>170.00</b> |

### Final Calculation

|                                           | SGD       | SGD                  |
|-------------------------------------------|-----------|----------------------|
| <b>Parts</b>                              | 10,582.00 |                      |
| Fixed Sundry Parts Price                  | 100.00    |                      |
| <b>Total Parts</b>                        |           | <b>10,682.00</b>     |
| <b>Labour Time Base 10 WU/h</b>           |           |                      |
| Total 178.0 WU X 42.00 SGD/h              | 747.60    |                      |
| <b>Total of Labour</b>                    |           | <b>747.60</b>        |
| <b>Total Of Extras</b>                    |           | <b>170.00</b>        |
| <b>Paint Work Time Base 10 WU/h</b>       |           |                      |
| Labour Cost 118.0 WU X 42.00 SGD/h        | 495.60    |                      |
| Material Cost                             | 258.89    |                      |
| <b>Total Paint Including Material</b>     |           | <b>754.49</b>        |
| <b>Repair Cost Excludes GST</b>           | 12,270.09 | <del>12,354.09</del> |
| GST (+9.00%)                              |           | 1,111.87             |
| <b>Repair Cost Included GST</b>           |           | <b>13,465.96</b>     |
| <b>Deductions (Excludes GST)</b>          |           |                      |
| Deduction For Excess                      | -2,000.00 |                      |
| <b>Total Of Deductions (Excludes GST)</b> |           | <b>-2,000.00</b>     |
| <b>Grand Total Excludes GST</b>           |           | <b>10,354.09</b>     |
| GST (+9.00%)                              |           | 931.87               |
| <b>Grand Total Included GST</b>           |           | <b>11,285.96</b>     |

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.

**Veron Chen (LKKAUTO)**

**From:** Cecilia Lee (CTPIS) <cecilia.lee@sg.cntaiping.com>  
**Sent:** Thursday, 6 February 2025 11:40 AM  
**To:** Veron Chen (LKKAUTO); Celine Fong (LKKAUTO); SUR; Huey Yon (LKKAUTO)  
**Cc:** Eddie Sim (CTPIS)  
**Subject:** RE: Request for Survey (OD) - SNN4330G / Mercedes Benz A200 DOA: 15.11.2024 - SNM24D206641/C01/LEEPG

[Confidential]

Hi Veron

Please check damage consistency and proceed with OD.

Insured involved in 2 accidents prior to the current case. 2<sup>nd</sup> RTA is a head-to-rear collision. Attached herewith TP SAS & VF for 1<sup>st</sup> and 2<sup>nd</sup> accident for damage consistency check.

☐ SNM24D206641 c01 LKK

Thanks & Best Regards,  
Cecilia Lee  
Claims Department

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Cecilia Lee (CTPIS)  
**Sent:** Friday, 17 January 2025 11:49 am  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Celine Fong (LKKAUTO) <celinefong@lkkauto.com>; SUR <sur@lkkauto.com>; Huey Yon (LKKAUTO) <hueyyon@lkkauto.com>  
**Cc:** Eddie Sim (CTPIS) <eddie.sim@sg.cntaiping.com>  
**Subject:** RE: Request for Survey (OD) - SNN4330G / Mercedes Benz A200 DOA: 15.11.2024 - SNM24D206641/C01/LEEPG

Hi Veron

We are still pending investigation clearance.

Thanks & Best Regards,  
Cecilia Lee  
Claims Department

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Sent:** Friday, 17 January 2025 10:33 am  
**To:** Cecilia Lee (CTPIS) <cecilia.lee@sg.cntaiping.com>; Celine Fong (LKKAUTO) <celinefong@lkkauto.com>; SUR