

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110607/RNP3E2
Date: 10/12/2024**REFERENCE**

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBJ7242X	Insured Vehicle No :	SKZ1985J
Date of Loss:	19/11/2024	Nature of Claim:	TP
		Claim No:	DMPC2401599H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ7242X		
Make & Model:	NISSAN NV350, 2.5 (A)	Engine No:	YD25055309B
Reg. Date:	29/07/2019 (Man. Year: 2019)	Chassis No:	JN1MC2E26Z0031486
Colour:	Black	Odometer:	160170 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 6 mm	Rear Left Side:	OHTSU 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	400.00	300.00	100.00	25.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	1,130.00	220.00	16.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,750.00	1,430.00	320.00	18.29
+ GST 9.00/9.00% (S\$)	157.50	128.70	28.80	18.29
Nett Amount (S\$)	1,907.50	1,558.70	348.80	18.29

INSPECTION

Date of Assignment:	28/11/2024	
Date Inspected:	29/11/2024	Inspected At: ETHOZ GROUP LTD 18 PANDAN ROAD SINGAPORE 609270
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Dec 2024)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ7242X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (NPA)	Repair	0.00 FN	*- FN
2	1		*B PILLAR LH (NPA)	Repair	0.00 FN	*- FN
3	1		*SLIDING DOOR LH (NPA)	Repair	0.00 FN	*- FN
4	1		*ROCKER PANEL LH (NPA)	Repair	0.00 FN	*- FN
5	1		*ADVERTISEMENT STICKER	Necessary	400.00 FS	*300.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					400.00	300.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)					0.00	0.00
Total Parts (S\$)					400.00	300.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO FACILITATE REPAIR	New	600.00	500.00
2	TO RESPRAY AFFECTED AREAS	New	700.00	600.00
3	RUST PROOFING	New	50.00	30.00
Gross Labour Cost (\$)			1,350.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >