

Not Authored
11 Rmp \$3300h

AAD2411-106

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9978D

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 NOV 2024

SHD9978D

JTDKB3FU003091252

200303878K

TOYOTA

PRIUS GEN 4

26/11/2024

GBB1330G/ China

3/8/2020

	PART
1	COVER, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	SUPPORT, FRONT BUMPER SIDE, RH
1	SUPPORT, RADIATOR, UPPER RH
1	MOULDING, FRONT BUMPER SIDE, RH
1	COVER, FRONT BUMPER HOLE, RH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	JAR ASSY, WINDSHIELD WASHER
1	HOOD SUB-ASSY
1	HINGE ASSY, HOOD, LH
1	HINGE ASSY, HOOD, RH
1	SUPPORT, RADIATOR, UPPER RH
1	SUPPORT SUB-ASSY, RADIATOR, RH
1	FENDER SUB-ASSY, FRONT RH
1	LINER, FRONT FENDER, RH
1	EMBLEM, SIDE PANEL, RH
1	UNIT ASSY, HEADLAMP, RH

	LIST
\$	Bz 653.31 ✓
\$	Sn 100.91 X
\$	R 902.16 A
\$	Or 100.49 ✓
\$	Sn 99.33 X
\$	CM 120.86 ✓
\$	Sn 38.22 X
\$	Sn 532.88 X
\$	Sn 224.70 X
\$	Sn 276.15 X
\$	R 1,243.20 X
\$	R 74.34 X
\$	R 74.34 X
\$	Bz 99.33 ✓
\$	R 308.91 X
\$	R 1,236.69 X
\$	Sn 255.36 X
\$	Sn 68.88 X
\$	ntf cm 3,325.56 ✓
TOTAL	\$ 9,735.62
25%	\$ 2,433.90
\$	\$ 7,301.71

Special Nett

AAD2411-106

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9978D

- 1 FRT BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 FRT BUMPER SIDE RETAINER CLIP

\$	<i>nn</i>	65.00	<i>65.00</i>
\$	<i>nn</i>	65.00	<i>X</i>
\$	<i>nn</i>	65.00	<i>X</i>
TOTAL	\$	195.00	

TOTAL PARTS	\$	7,496.71
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 250.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 1,800.00 *4401*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,000.00 *4001*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To transfer of rear fender panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL \$ 4,990.00****Over All Total \$ 12,486.71****(PART-BY-PART) Repair Days***07 Days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: