

ASS. REC. BY:

REF:

012 /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 99780

Yr Regn:

08.20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour MP White / Red

A/C: Insured / Std / NI / NA

Sp. Reading

821656

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

JTDK B31-U003091252

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size:

Goodride 195/65R15

R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

26/11/24

D.O.I.

21/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

01574

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) S + RS. SI

) F. P. S.

) Others

)

TOTAL

Report Format :

Imp Sum / I.B.I: (\$

NOT Withhold
1/10p 8

Trans-cab Auto Services Pte Ltd

AAD2411-106

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9978D

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 NOV 2024

SHD9978D

JTDKB3FU003091252

200303878K

TOYOTA

PRIUS GEN 4

26/11/2024

GBB1330G/ China

3/8/2020

PART		LIST	
1	COVER, FRONT BUMPER	\$	653.31 ✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	100.91 X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	902.16 ✓
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	100.49 ✓
1	SUPPORT, RADIATOR, UPPER RH	\$	99.33 X
1	MOULDING, FRONT BUMPER SIDE, RH	\$	120.86 ✓
1	COVER, FRONT BUMPER HOLE, RH	\$	38.22 X
1	GRILLE SUB-ASSY, RADIATOR	\$	532.88 X
1	GRILLE, RADIATOR, LOWER NO.1	\$	224.70 X
1	JAR ASSY, WINDSHIELD WASHER	\$	276.15 X
1	HOOD SUB-ASSY	\$	1,243.20 X
1	HINGE ASSY, HOOD, LH	\$	74.34 X
1	HINGE ASSY, HOOD, RH	\$	74.34 X
1	SUPPORT, RADIATOR, UPPER RH	\$	99.33 ✓
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	308.91 X
1	FENDER SUB-ASSY, FRONT RH	\$	1,236.69 X
1	LINER, FRONT FENDER, RH	\$	255.36 X
1	EMBLEM, SIDE PANEL, RH	\$	68.88 X
1	UNIT ASSY, HEADLAMP, RH	\$	3,325.56 ✓
TOTAL		\$	9,735.62
25%		\$	2,433.90
		\$	7,301.71

Special Nett

Trans-cab Auto Services Pte Ltd

AAD2411-106

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9978D

1 FRT BUMPER CLIP	\$	65.00	605a
1 FENDER LINER CLIP	\$	65.00	X
1 FRT BUMPER SIDE RETAINER CLIP	\$	65.00	X
TOTAL	\$	195.00	

TOTAL PARTS \$ 7,496.71**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	4401
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	4001
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	170.00	X
TOTAL	\$	4,990.00	

Over All Total \$ 12,486.71**(PART-BY-PART) Repair Days****87 Days****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: