

ASS. REC. BY:

REF:

C12 / 24110610 / kna3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S1TD 9978D Yr Regn: 08, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius C.G. 1798Colour MR. White / RW A/C: Insured / Std / NI / NASp. Reading 821656 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKB 31-U 003091252Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: Goodridge 195/65R15R: Wanli

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 26/11/24D.O.I. 22/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11/21 Eng @ 3300L Conkur

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Others

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

Not Authored
11 Nov 8330dp

AAD2411-106

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9978D

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 NOV 2024

SHD9978D

JTDKB3FU003091252

200303878K

TOYOTA

PRIUS GEN 4

26/11/2024

GBB1330G/China

3/8/2020

PART	
1	COVER, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	SUPPORT, FRONT BUMPER SIDE, RH
1	SUPPORT, RADIATOR, UPPER RH
1	MOULDING, FRONT BUMPER SIDE, RH
1	COVER, FRONT BUMPER HOLE, RH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	JAR ASSY, WINDSHIELD WASHER
1	HOOD SUB-ASSY
1	HINGE ASSY, HOOD, LH
1	HINGE ASSY, HOOD, RH
1	SUPPORT, RADIATOR, UPPER RH
1	SUPPORT SUB-ASSY, RADIATOR, RH
1	FENDER SUB-ASSY, FRONT RH
1	LINER, FRONT FENDER, RH
1	EMBLEM, SIDE PANEL, RH
1	UNIT ASSY, HEADLAMP, RH

LIST	
\$	B ₁ 653.31 ✓
\$	S ₁ 100.91 X
\$	R 902.16 A
\$	Ort 100.49 ✓
\$	S ₁ 99.33 X
\$	CM 120.86 ✓
\$	S ₁ 38.22 X
\$	S ₁ 532.88 X
\$	S ₁ 224.70 X
\$	S ₁ 276.15 X
\$	R 1,243.20 X
\$	R 74.34 X
\$	R 74.34 X
\$	B ₁ 99.33 ✓
\$	R 308.91 X
\$	R 1,236.69 X
\$	S ₁ 255.36 X
\$	na 68.88 X
\$	ntf cm 3,325.56 ✓
TOTAL	\$ 9,735.62
25%	\$ 2,433.90
	\$ 7,301.71

Special Nett

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2411-106

SHD9978D

- 1 FRT BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 FRT BUMPER SIDE RETAINER CLIP

\$	<i>nn</i>	65.00	<i>65.00</i>
\$	<i>nn</i>	65.00	<i>X</i>
\$	<i>nn</i>	65.00	<i>X</i>
TOTAL		\$	195.00

TOTAL PARTS \$ 7,496.71**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 250.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 1,800.00 *4401*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,000.00 *4001*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To transfer of rear fender panel fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL \$ 4,990.00****Over All Total \$ 12,486.71****(PART-BY-PART) Repair Days***87 Days**2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: