

Date: 28/11/2024

Vehicle No: SNK2496R

Model: TESLA MODEL Y

Chassis: LRWYHCFS4PC801879

Reg. Year: 2023

Not Withheld

Rekey B4 paint

4 days

84173.29

ESTIMATE

Third Party Insurer: MSIG

Third Party Veh No: SNR9103S

Date of Accident: 23/10/2024

Estimator: JONATHAN

Surveyor:

TP#2714

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOTLID			\$ <i>12</i> 1,219.62
	RR BUMPER			\$ <i>Buy</i> 836.44
	RR LOWER BUMPER			\$ <i>61</i> 542.05
	RR LOWER BUMPER REFLECTOR			\$ <i>12</i> 40.18
		2598.11	SUB TOTAL	\$ 2,638.29
		- 10%	Less 10%	\$ 263.83
		2338.29	PARTS TOTAL	\$ 2,374.46

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>na</i> 50.00
	RR W/SCREEN SEALANT			\$ <i>na</i> 100.00
	WRAP			\$ <i>(Bill)</i> 780.00
			S/N TOTAL	\$ 930.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas

\$ 600.00

To perform wiring checks on electrical systems

\$ 30.00

To remove, putty, repair, sand and respray affected areas

\$ 400.00

To remove, replace & reinstall Bootlid inner mechansim

\$ 30.00

To perform Adas Checks, Calibration & Programming

\$ *na* 200.00

To remove, refix & replace RR Windscreen

\$ 120.00

965 LABOUR TOTAL \$ 1,380.00

TOTAL \$ 4,684.46

JONATHAN

PARTS: 2338.29

S/N: 870

LABOUR: 965

TOTAL: 4173.29

Lumina Wrap
18 Boon Lay Way #04-98
Singapore
Singapore 609966
luminawrapsg@gmail.com



BILL TO			DATE	27/11/2024	
Mr John			TERMS	COD	
SNK2496R			DUE DATE	27/11/2024	
TESLA MODEL Y					
DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
27/11/2024	Rewrap Service	Back Bumper And Boot Rewrap Service (Self Healing Ferrari Red)	1	780.00	780.00
Full Payment Upon Car Collection					
BALANCE DUE					S\$780.00