

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Desmond Lee Kerr Wen

Date: 05 Dec 2024

Preliminary Advice

Insured Vehicle No	: SNR9103S	Accident Date	: 24/10/2024
TP Vehicle No	: SNK2496R	Assignment Date	: 28/11/2024
Make	: TESLA MODEL Y RWD	Est. Duration of Repair	: 4
Date of Inspection	: 03/12/2024		
Inspection At	: OPTIMA WERKZ PTE LTD (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-05/06 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,684.46
Revised Amount	:S\$	3,393.30
Check Items (Estimated)	:S\$	980.00
Total	:S\$	4,373.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- ☐ The vehicle is economical for repair
- ☐ The vehicle is not economical for repair
- ☒ Part-by-Part repair
- ☐ Lump Sum repair

- ☒ The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.