

Date: 28/11/2024

Vehicle No: SNK2496R

Model: TESLA MODEL Y

Chassis: LRWYHCFS4PC801879

Reg. Year: 2023

Not Withheld

Rekey B& paint

4 days

Third Party Insurer: MSIG

Third Party Veh No: SNR9103S

Date of Accident: 23/10/2024

Estimator: JONATHAN

Surveyor:

4173.29

TP#2714

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOTLID			\$ <i>12</i> 1,219.62
	RR BUMPER			\$ <i>Buy</i> 836.44
	RR LOWER BUMPER			\$ <i>60</i> 542.05
	RR LOWER BUMPER REFLECTOR			\$ <i>12</i> 40.18
		2598.11	SUB TOTAL	\$ 2,638.29
		- 10%	Less 10%	-\$ 263.83
		2338.29	PARTS TOTAL	\$ 2,374.46

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>10</i> 50.00
	RR W/SCREEN SEALANT			\$ <i>10</i> 100.00
	WRAP			\$ <i>(B711)</i> 780.00
			S/N TOTAL	\$ 930.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas

\$ 600.00

To perform wiring checks on electrical systems

\$ 30.00

To remove, putty, repair, sand and respray affected areas

\$ 400.00

To remove, replace & reinstall Bootlid inner mechansim

\$ 30.00

To perform Adas Checks, Calibration & Programming

\$ 200.00

To remove, refix & replace RR Windscreen

\$ 120.00

965

LABOUR TOTAL \$ 1,380.00

TOTAL \$ 4,684.46

JONATHAN

PARTS: 2338.29
S/NET: 870
LABOUR: 965
TOTAL: 4173.29

Lumina Wrap

18 Boon Lay Way #04-98
Singapore
Singapore 609966
luminawraps@gmail.com



BILL TO
Mr John
SNK2496R
TESLA MODEL Y

DATE 27/11/2024
TERMS COD
DUE DATE 27/11/2024

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
27/11/2024	Rewrap Service	Back Bumper And Boot Rewrap Service (Self Healing Ferrari Red)	1	780.00	780.00

Full Payment Upon Car Collection

BALANCE DUE

S\$780.00