

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6 #01-40/#01-63 Autobay Singapore 417883

Tel: 6747-4810 6741-0879

Fax: 6745-5018

cmm@cmm.sg

Reg. No. 20561400X

Our Ref: EST173/24/TP

Your Ref: To Be Advised

26-Nov-24

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Madam

Re: Final cost of repair to Toyota Hiace no: GBJ1962R

Date of accident: 23-11-2024

Parts Supply:

1 pc Tailgate <i>Revised</i>		SS	2,120.40 ✓
1 pc Tailgate weatherstrip <i>new</i>	3469.80		285.60 +
1 pc Tailgate inner lock <i>Revised</i>			316.50 ✓
1 pc Tailgate emblem <i>new</i>			32.10 ✓
2 pcs Tailgate hinge @\$85.10 <i>3 new</i>	2602.35		170.20 +
2 pcs Tailgate stopper @\$42.50			85.00 +
1 pc Rear bumper <i>Revised</i>			575.20 ✓
2 pcs Rear bumper retainer @\$45.30 <i>3 new</i>			90.60 +
2 pcs Rear bumper bracket @\$65.40			130.80 +
6 pcs Rear bumper clips @\$4.50 <i>new</i>			27.00 ✓
1 pc Rear end panel <i>Revised</i>			425.60 ✓
			4,259.00
		Less 25%	(1,064.75)
			3,194.25

S/Nett items:

1 pc Tailgate sticker - CERTIS CISCO <i>3 new</i>		80.00 ✓
1 pc Tailgate sticker - Certisgroup.com		80.00 ✓
1 pc Tailgate sticker - Tel: 18007472888		80.00 ✓
1 pc Tailgate sticker - 70km/h <i>new</i>		12.00 ✓
1 pc Rear no plate <i>new</i>		20.00 +
1 set Reverse sensor (4 pcs) <i>Revised</i>		250.00 <i>20</i>
		SS 3,716.25

TP ALG.

Xiao Tong

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6 #01-40/#01-63 Autobay Singapore 417883

Tel: 6747-4810 6741-0879

Fax: 6745-5018

cmm@cmm.sg

Reg. No. 20561400X

Our Ref: EST173/24/TP

26-Nov-24

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Madam

Re: Final cost of repair to Toyota Hiace no: GBJ1962R

Parts Supply:

Balance b/f

S\$ 3,466.25

Labour Charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove & refit tailgate windscreen.

To remove & install rear reverse sensor.

To check wirings.

900.00 ~~700~~

800.00 ~~600~~

120.00 ✓

60.00 ~~50~~

30.00 ✓

S\$ 5,376.25

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li

W/S 26/11/24

05 Days

Total: 4554.35

W/S: 3.6K