

(25/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ FC/ 24110615/Unp3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 39435at Workshop m/s SMH

of _____

Insured: SHC 1299m

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$5800

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 21 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 414d

Date: _____ Vehicle: IN / OUT

Person Contacted: 27A 81431Veh No: FBM 39435 Yr Regn: 31/10/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or TFX150Make: Yamaha XABRE c.c. 150Colour: Green A/C: Insured / Std / NI / NASp.Reading: 81811 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3RG 3710HK 026728Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 110-70R17R: 140-70R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. 6 mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 26/11/24 D.O.I. 29/11/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear, 1/5 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dsp 26.

15/5/24 4/5 \$1140 in hand Stephanie

(Red, \$1091, 48%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:		Singapore NRIC
Owner ID:		414D
Vehicle Details		
Vehicle No.:		FBM3943S
Vehicle to be Exported:		No
Intended Deregistration Date:		29 Nov 2024
Vehicle Make:		YAMAHA
Vehicle Model:		XABRE TFX150
Primary Colour:		Green
Manufacturing Year:		2017
Engine No.:		G3G8E0035920
Chassis No.:		MH3RG3710HK026728
Maximum Power Output:		-
Open Market Value:		\$2,617.00
Original Registration Date:		31 Oct 2017
First Registration Date:		31 Oct 2017
Transfer Count:		3
Actual ARF Paid:		\$393.00
Intended PARF Rebate Details		
PARF Eligibility:		No
PARF Eligibility Expiry Date:		-
PARF Rebate Amount:		\$0.00
Intended COE Rebate Details		
COE Expiry Date:		30 Oct 2027
COE Category:		D - Motorcycle
COE Period(Years):		10
QP Paid:		\$4,903.00
COE Rebate Amount:		\$1,431.00
Total Rebate Amount:		\$1,431.00
Message		
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.		

The information contained herein is correct as at 29 Nov 2024


OK

Vehicle Details

Vehicle No.	Make / Model
FBM3943S	YAMAHA / XABRE TFX150
Vehicle Type :	Vehicle Attachment 1 :
P00 - Passenger Motorcycle/Autocycle /Moped	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	MH3RG3710HK026728
Propellant :	Engine No. :
Petrol	G3G8E0035920
Motor No. :	Engine Capacity :
-	150 cc
Power Rating :	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
285 kg	135 kg
Year Of Manufacture :	Original Registration Date :
2017	31 Oct 2017
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$4,903.00	30 Oct 2027
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
30 Apr 2025	-
Inspection Due Date :	Intended Transfer Date :
30 Oct 2025	27 Nov 2024
CO2 Emission :	CEV/VES Rebate Utilised Amount :
-	-

Advertisement

Motorcycles > Motorcycles for Sale > Class 2B



YAMAHA MT15 XABRE

S\$5,499

Used

Meetup

First Centre

Description

Posted 3 days ago

Make Yamaha

Type Road Bike

 **YAMAHA MT15 V1 XABRE**
COE: 27 Mar 2027 (Renewable)
First registered: 28 Mar 2017
Open Market Value: \$2,727.00
PQP Paid : \$7,483.00

Upgrades/Add on:

read more

Meet-up

First Centre



JOYRIDE . @joyridemotorcycle
5.0 (44 reviews)

Chat

Sign in to make offer

S\$ 5499

Make Offer

Returns and refunds

Depends on the seller's decision. Not covered by Buyer Protection.

Safety policy

Pay only at the meet-up. Transferring money directly to strangers puts you at risk of e-commerce scams.

Advertisement



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

3035 / Ah Long

QUOTATION

Customer :

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

ATTN: MS FIRST CAPITAL INSURANCE LTD

VEHICLE NO. : FBM3943S
MAKE/MODEL : YAM / XABRE TFX150

NO. : 48395

DATE : 28/11/2024
CLAIM NO. : 12665
POLICY NO. : PNMC2024-00002887

FROM : STEPHANIE

*Not Advised
in
motor
1/5 #1140
3 days
29/11/24
to be, h. - MEAN*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BEARING STEERING CONE LOWER P/N: 56456 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
2	BEARING STEERING CONE UPPER P/N: 56209 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
3	BEARING SWING ARM P/N: 74736 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$20.00	40.00
4	BOX REAR (KAPPA) K39N P/N: 82709 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$279.00	279.00
5	BUSH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$22.00	22.00
6	CAP SWING ARM P/N: 74738 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	16.00
7	COVER SIDE 1 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$51.00	51.00
8	COVER SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00	39.00
9	COVER UNDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00	59.00



S/N	Description	Action	Qty	Unit Price	Amount
10	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	me 16.00
11	FOOTREST FRONT LEFT P/N: 80461 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	cu 23.00
12	FOOTREST REAR LH P/N: 80532 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	cu 23.00
13	HANDLE GUARD CARBON - (REPORTED BY MECHANIC)	REPLACE	1.00	\$124.00	cu 124.00
14	LABOUR P/N: 06766	* Supply/Install	8.00	\$85.00	350 680.00
15	LEVER SET RCB (GOLD) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$124.00	cre 124.00
16	MID RACE BALL P/N: 18585 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	su 12.00
17	MID RACE BALL P/N: 18576 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	ny 12.00
18	MIRROR LH P/N: 55793 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$26.00	cu 26.00
19	MUDGUARD REAR P/N: 77237 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$20.00	dis 20.00
20	PEDAL GEAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.00	cu 39.00
21	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$29.00	su 29.00
22	PLATE REAR MUDGUARD P/N: 77241 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	dis 85.00
23	RETAINER BALL BEARING P/N: 55218 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	ny 12.00
24	SEAL DUST STEERING CONE P/N: 59783 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$8.00	m 8.00
25	SIGNAL REAR LH ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	cu 28.00



S/N	Description	Action	Qty	Unit Price	Amount
26	SLIDER FRONT WHEEL (GOLD) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$124.00	124.00
27	SPEEDOMETER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$248.00	248.00
28	STAND SIDE P/N: 84959 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$23.00	23.00
29	STICKER 3 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
30	STICKER 5 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
SUB TOTAL					\$2,231.00
GST @ 9 %					\$200.79
GRAND TOTAL (SGD)					\$2,431.79

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



STEPHANIE

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21199
- 102
1079.10
360
1428.1
203
1143

